



BAN HOCK HIN
Co., Pte Ltd

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

4th Sep 2024

Accident Involving FBG4591Z & SML6925A on 19 Aug 24

LKK REF: CD/III24090003/Uma3

I am writing to inform you that, following a thorough assessment, our client's vehicle has been deemed beyond economic repair. The damage sustained from the accident has resulted in extensive costs that exceed the vehicle's current market value at \$ 5k.

Therefore, we have decided not to proceed with repairs.

Attached is the Deregister Letter.

Please let me know the next steps to finalize this matter.

Thanks.

Sh.

Regards
Stephanie Gan
Insurance Manager

LKK Auth Consultant's hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- To spray damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



bizSAFE₃



Address: Blk 8, Defu South Street 1, #04-28, JTC Defu Industrial City, Singapore 533758 | Telephone: +65 6281 6520
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO 2002-1-0383
ISO 9001 2015