

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GZ 9473P

	REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	REAR DOOR N/S	DENTED/BENT	\$2,120.14	\$1,925.10	
1	SET REAR DOOR TRIMBOARD CLIP	NOT NECESSARY	\$50.00	\$0.00	
1	REAR DOOR ROLLER (BOTTOM)	NOT NECESSARY	\$357.67	\$0.00	
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	\$1,086.26	\$0.00	
1	REAR BUMPER SIDE RETAINER N/S	NOT NECESSARY	\$71.80	\$0.00	
1	REAR BUMPER	NOT NECESSARY	\$776.03	\$0.00	
1	REAR CORNER GARNISH N/S	NOT NECESSARY	\$220.09	\$0.00	
	LESS 25.00% DISCOUNT		(\$1,170.50)	(\$481.28)	
		\$3,511.49	\$1,443.82		

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR RIM COVER N/S (SN)	TO REPAIR SEE LABOUR	\$120.00	\$0.00
1	REAR DOOR BLACK PROTECTIVE LINING N/S (SN)	CUT	\$80.00	\$60.00
			\$200.00	\$60.00

Description of Parts  Condition  Workshop Estimate (\$) Our Adjusted (\$)  TO CHECK DOOR WIRING SYSTEM  \$80.00 \$20.00  TO TRANSFER RHR DOOR COMPONENTS FROM OLD DOOR TO NEW DOOR  TO APPLY ANTI-RUSTING COATING ON PANELS  LABOUR TO REMOVE, CUT, CHANGE & PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER N/S AND REAR RIM COVER N/S  TO PUTTY AND RESPRAY AFFECTED AREAS	Labour				
TO TRANSFER RHR DOOR COMPONENTS FROM OLD DOOR TO NEW DOOR  TO APPLY ANTI-RUSTING COATING ON PANELS  LABOUR TO REMOVE, CUT, CHANGE & PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER N/S AND REAR RIM COVER N/S  TO PLITTY AND RESPRAY AFFECTED AREAS		Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
NEW DOOR  TO APPLY ANTI-RUSTING COATING ON PANELS  LABOUR TO REMOVE, CUT, CHANGE & PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER N/S AND REAR RIM COVER N/S  TO PLITTY AND RESPRAY AFFECTED AREAS.  \$120.00 \$30.00  \$400.00		TO CHECK DOOR WIRING SYSTEM		\$80.00	\$20.00
LABOUR TO REMOVE, CUT, CHANGE & PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER N/S AND REAR RIM COVER N/S  TO PUTTY AND RESPRAY AFFECTED AREAS.  \$120.00 \$30.00 \$400.00				\$120.00	\$50.00
INCLUSIVE OF THE RÉPAIR OF REAR FENDER N/S AND REAR RIM \$1,500.00 \$400.00		TO APPLY ANTI-RUSTING COATING ON PANELS		\$120.00	\$30.00
TO PUTTY AND RESPRAY AFFECTED AREAS		INCLUSIVE OF THE REPAIR OF REAR FENDER N/S AND REAR RIM		\$1,500.00	\$400.00
\$1,200.00		TO PUTTY AND RESPRAY AFFECTED AREAS		\$1,200.00	\$500.00
\$3,020.00 \$1,000.00			\$3,020.00	\$1,000.00	

GRAND TOTAL	\$6,731.49	\$2,503.82		
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$2,000.00		
Report Ref No: CS/INC24090004/Unh3				

TOTAL FOR SPARE PARTS: \$ 3,711.49 \$ 1,503.82
TOTAL FOR LABOUR: \$ 3,020.00 \$ 1,000.00
TOTAL REPAIR COST: \$ 6,731.49 \$ 2,503.82



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## **CKS**

MARCUS CHUA KANG SENG Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.