



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24090004/Unh3
75 BRAS BASAH ROAD	Date:	24/09/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBK 8078S	Veh. Inspected	GZ 9473P
Policy No.	-	Coverage	0
Claim No.	MT/1292754-002	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	30/08/2024

### 2. Vehicle Details

Make & Model	TOYOTA HIACE	C.C	2982
Engine No.	1KD1534178	Year of Reg.	30/11/2006
Chassis No.	JTFHT02P700001156	Colour	WHITE
Odometer	368419 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	TRANSMATE	8
L/H Front Tyre	195R15	TRANSMATE	8
R/H Rear Tyre	195R15	HABILEAD	8
L/H Rear Tyre	195R15	HABILEAD	8

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	27/08/2024	Inspection Date	11/09/2024 (09:31)
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days