

LEANG AUTOMOTIVE
BLK 1 KAKI BIKIT AVE 6 #01-68
AUTOBAY S'PORE 417883 HP 90286516

VEHICLE No : SLT 2510J

1PC	REAR BUMPER	1011	\$1,130.00	✓
1PC	REAR BUMPER REFLECTOR O/S	one	\$68.00	✓
1PC	REAR BUMPER PDC SENSOR O/S	su	\$198.00	X
1PC	REAR BUMPER TOW COVER O/S	mi	\$32.00	✓
1SET	REAR BUMPER CLPIS	ken	\$50.00	✓
1PC	REAR BUMPER BEAM	DD	\$711.00	✓
1PC	REAR BUMPER SIDE RETAINER O/S	11	\$112.00	X
1PC	REAR END PANEL	DD	\$780.00	✓
1PC	BOOTLID	11	\$1,350.00	X
1PC	REAR EXHAUST ASSY	su	\$1,820.00	X
			\$6,251.00	
		LESS 10%	\$5,625.90	

TO CHECK WIRING	refix	\$50.00	20
TO DISMANTLE & REPLACED REAR PDC SENSOR		\$50.00	30
TO SPRAY RUST PROOFING		\$90.00	30
TO DISMANTLE & REFIX SEAT ,CUSHION HOLSTERY		\$100.00	60
TO DISMANTLE & REFIX REAR EXHAUST	un	\$100.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$950.00	600
TO PUTTY & SPRAY PAINTING		\$1,000.00	540
TOTAL		\$7,965.90	

Not Authorised
in
mura's

2/9/24

2/5 & 3000/

4 days

the up-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-2771
103
2493.90
1260
37739
202
3019