



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: Date: Code:	CS/FCI24090008/Knp3m4 11/09/2024 FCI2
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 2694Z	Veh. Inspected	SHB 7542B
	Policy No.	D-24101861MFCT	Coverage	0
	Claim No.	D24003885MFCT	Excess	\$0.00
	Assign From	AINI	Assign Date	30/08/2024
2. Vehicle Details				
	Make & Model	TOYOTA PRIUS (AUTO)	C.C	1798
	Engine No.	2ZR2C24106	Year of Reg.	31/05/2019
	Chassis No.	JTDKB3FU603081082	Colour	M.P. WHITE / RED
	Odometer	433748 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: STANDARD ALLOY RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	195/65R15	SAILUN	7
	L/H Front Tyre	195/65R15	SAILUN	7
	R/H Rear Tyre	195/65R15	SAILUN	7
	L/H Rear Tyre	195/65R15	SAILUN	7
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	28/04/2024	Inspection Date	02/09/2024
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD - NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				