

ASS. REC. BY:

REF:

FC2 /

CS/FC124090008 / Knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

1.31

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 7542B

Yr Regn:

05, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Prius

C.C.

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

433 748

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU803081082

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Pajero

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

28/4/24

D.O.I.

2/9/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 15m

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/9 8630.95 Cash (Red. \$10853.09, 94%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHB7542B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Apr 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2C24106
Chassis No.:	JTDKB3FU603081082
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	31 May 2019
First Registration Date:	31 May 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2027
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	30 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,309.00
COE Rebate Amount:	\$8,590.00
Total Rebate Amount:	\$19,275.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Apr 2024

OK

Not Notified
\$ 630.95

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7542B

AAD2404-142

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

02 SEP 2024

SHB7542B

JTDKB3FU603081082

200303878K

TOYOTA

PRIUS

28/4/2024

SHC2694H/FCI

31/5/2019

PART

LIST

1	COVER, FRONT BUMPER	\$	Pin n	516.00	X
1	ABSORBER, FRONT BUMPER ENERGY	\$	Pin	100.17	} X
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	n	902.16	
1	SUPPORT, FRONT BUMPER SIDE, LH	\$	Pin	100.49	
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	Pin	100.49	
1	STAY SUB-ASSY, FRONT BUMPER, LH	\$	Pin	59.85	
1	STAY SUB-ASSY, FRONT BUMPER, RH	\$	Pin	59.85	
1	ABSORBER, FRONT BUMPER ENERGY	\$	Pin	100.17	
1	ABSORBER, FRONT BUMPER, LOWER	\$	Pin	167.37	
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	n	902.16	
1	FRONT BUMPER SIDE RETAINER RH	\$	Pin	80.10	} X
1	JAR ASSY, WINDSHIELD WASHER	\$	Pin	219.10	
1	UNIT ASSY, HEADLAMP, RH	\$	Pin	2,637.60	
1	LAMP ASSY, FOG, RH	\$	Pin	1,200.78	
1	FENDER SUB-ASSY, FRONT RH	\$	n	977.80	
1	LINER, FRONT FENDER, RH	\$	Pin	206.70	} X
1	FRONT FENDER EMBLEM RH	\$	n	54.60	

TOTAL	\$	8,385.38
25%	\$	2,096.35
	\$	6,289.04

Special Nett

1	FRT BUMPER CLIP	\$	n n	65.00	X
1	FRT BUMPER SIDE RETAINER CLIP	\$	n n	65.00	X

Trans-cab Auto Services Pte Ltd**AAD2404-142**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7542B

1 FENDER LINER CLIP X NN

	\$	75.00
TOTAL	\$	205.00

TOTAL PARTS	\$	6,494.04
--------------------	-----------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,800.00	440/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To Check Electrical Lighting Concerned.	\$	nn	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,000.00	150/
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To transfer of front fender panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X

TOTAL	\$	4,990.00
--------------	-----------	-----------------

Over All Total	\$	11,484.04
-----------------------	-----------	------------------

(Lump Sum) Repair Days**08 Days***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: