

Not Attached  
\$ 630.95

AAD2404-142

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111  
Tel No. : 6287 6666 Fax No. : 6257 1330  
CO./GST Reg. No. 201019626G

**SHB7542B**

Vehicle No.:  
Chassis No.:  
Co UEN:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration:

02 SEP 2024

**SHB7542B**

JTDKB3FU603081082  
200303878K  
TOYOTA  
PRIUS  
28/4/2024  
**SHC2694H/FCI**  
31/5/2019

PART	LIST
1 COVER, FRONT BUMPER	\$ Pin n 516.00 X
1 ABSORBER, FRONT BUMPER ENERGY	\$ Pin 100.17
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ R 902.16
1 SUPPORT, FRONT BUMPER SIDE, LH	\$ Pin 100.49
1 SUPPORT, FRONT BUMPER SIDE, RH	\$ Pin 100.49
1 STAY SUB-ASSY, FRONT BUMPER, LH	\$ Pin 59.85
1 STAY SUB-ASSY, FRONT BUMPER, RH	\$ Pin 59.85
1 ABSORBER, FRONT BUMPER ENERGY	\$ Pin 100.17
1 ABSORBER, FRONT BUMPER, LOWER	\$ Pin 167.37
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ R 902.16
1 FRONT BUMPER SIDE RETAINER RH	\$ Pin 80.10
1 JAR ASSY, WINDSHIELD WASHER	\$ Pin 219.10
1 UNIT ASSY, HEADLAMP, RH	\$ Pin 2,637.60
1 LAMP ASSY, FOG, RH	\$ Pin 1,200.78
1 FENDER SUB-ASSY, FRONT RH	\$ R 977.80
1 LINER, FRONT FENDER, RH	\$ Pin 206.70
1 FRONT FENDER EMBLEM RH	\$ n 54.60 ✓

<b>TOTAL</b>	\$	<b>8,385.38</b>
<b>25%</b>	\$	<b>2,096.35</b>
	\$	<b>6,289.04</b>

**Special Nett**

1 FRT BUMPER CLIP	\$	nn 65.00 X
1 FRT BUMPER SIDE RETAINER CLIP	\$	nn 65.00 X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**AAD2404-142**

**SHB7542B**

1 FENDER LINER CLIP

	\$	75.00
<b>TOTAL</b>	<b>\$</b>	<b>205.00</b>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>6,494.04</b>

**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>na</i> 250.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	<i>440/</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	<i>na</i> 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	<i>150/</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To transfer of front fender panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X

**TOTAL \$ 4,990.00**

**Over All Total \$ 11,484.04**

**(Lump Sum) Repair Days**

**08 Days**

*2 days*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: