

Name & Address:

Motor Claims Department

ETIQA INSURANCE BERHAD

ONE RAFFLES QUAY

#22-01 NORTH TOWER

SINGAPORE 048583

Email/Tax No:

Contact No:

Vehicle No:

SKT1398K

Brand & Model:

Macan S

Chassis/VIN No:

WP1ZZZ95ZFLB67248

WIP#

11497

Date:

29 Aug 24

Franchise:

PORSCHE

Contact Person (Eurokars):

FAIZ

Contact No (Eurokars):

6331 0680

Type of Claim:

THIRD PARTY

YEAR MODEL:

12/02/2015

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR DOOR LH <i>repair</i>	P95B-833-021-B -GRV	1		-	\$ 2,666.90
2	DOOR SEAL OUTER LH <i>XXnn</i>	P95B-839-911- -	1		-	\$ 301.00
3	DOOR SEAL C PILLAR LH <i>XXnn</i>	P95B-839-761-B -	1		-	\$ 230.90
4	CLIP <i>XXnn</i>	P95B-837-069- -	8		-	\$ 32.80
5	DOOR SEAL LOWER LH <i>XXnn</i>	P95B-839-119-B -	1		-	\$ 175.30
6	REAR DOOR HANDLE LH <i>XXnn</i>	P95B-837-205-D -G2X	1		-	\$ 593.10
7	EXPANDER NUT <i>XXnn</i>	PN -106-213-01-	2		-	\$ 5.40
8	REAR DOOR LOWER TRIM LH <i>XXnn</i>	P95B-898-565 -OK1	1		-	\$ 710.20
9	REPAIR KIT <i>XXnn</i>	P95B-898-633- -	1		-	\$ 136.90
10	STONE GUARD LH <i>XXnn</i>	P95B-854-931-A -	1		-	\$ 109.00
11	CLIP <i>XXnn</i>	P8K0-837-199- -	8		-	\$ 10.40
12	PROTECTIVE FILM REAR FENDER <i>XXnn</i>	P95B-853-225-A -	1		-	\$ 87.50
13	SIDE SKIRT LH <i>XXnn</i>	P95B-853-563- -1E0	1		-	\$ 324.80
14	SOUND ABSORBER FOR SIDE SKIRT LH <i>XXnn</i>	P95B-857-993-A -	1		-	\$ 48.80
15	ALLOY WHEEL TITANIUM REAR LH <i>XXnn</i>	P95B-601-025-DT-OC6	1		-	\$ 4,253.50
16						\$ -

Sub-Total (Parts Price) \$ - \$ 9,686.50

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE REAR DOOR LH, SIDE SKIRT LH & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR REAR FENDER LH & ALL AREAS AFFECTED BY THE ACCIDENT.	3440	\$ 5,160.00
2	TO RESPRAY REAR DOOR LH, REAR FENDER LH	2400	\$ 3,000.00
3	TO CARRY OUT BODY CAVITY PRESERVATION.	150	\$ 200.00
4	TO REPLACE 1 PC TYRE REAR LH	nett <i>XXnn</i>	\$ 1,200.00
5	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	nett	\$ 120.00
6	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	nett	\$ 680.00
7	TO TRANSFER THE REAR DOOR LH MECHANISM	nett	\$ 860.00

REPAIR ESTIMATE

8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 600.00
10	SUNDRIES	nett	\$ 20.00

Survey Date & Time: 04/09/24	Repair Days: 5 days	Excess:
--	-------------------------------	---------

Surveyor Remarks:

*Panel
Hx 200x150
Resy by paint*

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ - \$ 12,170.00

	REVISED	PRICE
Parts Price	\$ -	\$ 9,686.50
Labour Price	\$ -	\$ 12,170.00
Total (Initial Estimate)	\$ -	\$ 21,856.50
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 21,856.50
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 21,856.50
GST 9%	\$ -	\$ 1,967.09
GRAND TOTAL	\$ -	\$ 23,823.59

8420

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: