

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

Irfan Akram
Blk 872 Tampines St 84
03 - 93
Singapore 520872

Not Withheld
11 Day @ 1250/h
Recovery After Paim
3 days

Vehicle No : SMW 5303 T
Make : Nissan Note
Year :

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear n/s tail-lamp	
1 pc	Rear bumper	612.20
1 pc	Rear n/s bumper side retainer	

<i>W</i>	\$480.00	<i>✓</i>
<i>mg cm</i>	\$688.00	<i>✓</i>
<i>Pr</i>	\$55.00	<i>x</i>
	\$1,223.00	
Less 10 %	\$122.30	
	\$1,100.70	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$500.00 *200h*

To putty & spray paint on accident affected portion.

\$500.00 *400h*

Check/reconnect wiring.

\$30.00 *20h*

Total \$2,130.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: