

Wheelz 4 You

To: Motor Claims Department

Vehicle No: SLD3903L

Model: TOYOTA CAMRY

ESTIMATE For SLD3903L TOYOTA CAMRY

Not Authorized
no money
2/9/24
L/S \$5700
5 days

Date: 02/09/2024

L/S \$5700

QTY	Parts	Amount
1	RH REAR DOOR <i>cut/but</i>	\$ 1,450.00 ✓
1	RH REAR DOOR TAPE <i>neu</i>	\$ 60 138.00 ✓
1	RH REAR DOOR WEATHERSTRIP <i>11X</i>	\$ 259.00 X
1	RH REAR DOOR LOCK <i>neu</i>	\$ 651.00 X
1	RH SIDE SKIRT <i>cut/but</i>	\$ 590.00 ✓
1	RH REAR FENDER <i>neu</i>	\$ 869.00 X
1	RH REAR FENDER INNER SHIELD <i>11X</i>	\$ 311.00 X
1	REAR BUMPER <i>cut/but</i>	\$ 723.00 ✓
1	RH REAR BUMPER SIDE RETAINER <i>11X</i>	\$ 143.00 X
1	RH REAR RIM <i>cut</i>	1600 \$ 1,976.00 ✓
1	RH REAR SHOCK ABSORBER <i>but</i>	392.20 \$ 404.00 ✓
1	RH REAR WHEEL BEARING <i>Page</i>	\$ 633.00 ✓
1	REAR WINDSCREEN MOULDING <i>11X</i>	\$ 198.00 X
1	RH WING MIRROR <i>one/eye</i>	1450.20 \$ 1,639.00 ✓
Parts Sum:		\$ 9,984.00
Parts Less 25% :		\$ 2,496.00
Parts Total:		\$ 7,488.00
Special Nett Items		
1	RH REAR DOOR INNER TRIM CLIPS <i>11 X</i>	\$ 40.00 X
1	RH REAR FENDER INNER SHIELD CLIP <i>11 X</i>	\$ 40.00 X
1	RH SIDE SKIRT CLIP <i>neu</i>	\$ 40.00 ✓
1	REAR BUMPER CLIPS <i>neu</i>	\$ 40.00 ✓
1	REAR BUMPER RIVET <i>11 X</i>	\$ 40.00 X
1	REAR WINDSCREEN INNER SEAL <i>11 X</i>	\$ 80.00 X
1	REAR WINDSCREEN SEALANT <i>11 X</i>	\$ 40.00 X
Special Nett Items Total:		\$ 320.00

Labour & Misc Charges

Description	Amount
TO CHECK REAR PORTION WIRING	\$ 50.00 20
TO FIT REVERSE SENSOR ON NEW BUMPER	\$ 50.00 30
TO RESET PDC	\$ 11 350.00 X
TO TRANSFER RH REAR DOOR GLASS	\$ 120.00 50
TO TRASNFER RH REAR DOOR MECHANISM	\$ 120.00 }
TO RE-CALIBRATE RH REAR CENTRAL LOCKING	\$ 250.00 }
TO RE-CALIBRATE RH REAR POWER WINDOW	\$ 250.00 }
TO TRASNFER RH REAR TYRE ON NEW RIM PLUS BALANCING	\$ 11 50.00 X

TO REPLACE RH REAR UNDERCARRIAGE	\$	350.00	150
TO CONDUCT 4 WHEEL ALIGNMENT	\$	120.00	80
TO REMOVE/REFIX REAR WINDSCREEN	\$	120.00	x
TO REMOVE/REFIX INNER TRIM, GARNISHES TO FACILITATE REPAIR	\$	250.00	60
TO PANEL BEAT AND REPLACEMENT OF PARTS	\$	1,200.00	580
TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	\$	1,200.00	1000
Labour Charges Total:	\$	4,480.00	

Parts Total: \$ 7,488.00
Special Nett Items Total: \$ 320.00
Labour Charges Total: \$ 4,480.00
Total Cost Of Repair: \$ 12,288.00
(Non-Inclusive of GST)

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged parts before resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-68982
 252
 517365
 80
 1970
 722365
 202
 8778.