

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

Not Authorised

all  
items

2/9/24

d/c \$ 7600

10 days

VEHICLE No: SM9455X

|      |                                     |                |                |             |
|------|-------------------------------------|----------------|----------------|-------------|
| 1PC  | REAR WINDSCREEN                     | 11             |                | \$850.00 X  |
| 1PC  | REAR WINDSCREEN MOULDING            | 111            | 60.00          | \$125.00    |
| 1PC  | TAILGATE                            | Body, 20       | 931.50         | \$1,545.15  |
| 1PC  | TAILGATE REAR LOGO                  | 111            | 82.00          | \$96.00     |
| 1PC  | TAILGATE 'SWIFT' EMBLEM             | 111            | 80.00          | \$92.00     |
| 1PC  | TAILGATE 'SUZUKI' EMBLEM            | 111            | 80.00          | \$88.00     |
| 1PC  | TAILGATE INNER TRIM                 | 11             |                | \$450.15 X  |
| 1SET | TAILGATE INNER TRIM CLIPS           | 11             |                | \$48.00 X   |
| 1PC  | TAILGATE INNER HANDLE GARNISH       | 111            |                | \$288.15    |
| 1PC  | TAILGATE INNER LOCK                 | 111            | 280.60         | \$465.00    |
| 1PC  | TAILGATE WEATHERSTRIP               | 111            | 190.65         | \$280.00    |
| 1PC  | TAILGATE REAR WIPER MOTOR           | 11             |                | \$660.15 X  |
| 2PCS | TAILGATE DAMPERS @\$105.00          | 11             |                | \$210.00 X  |
| 1PC  | REAR BUMPER                         | Dis            | 810.00         | \$1,450.15  |
| 2PCS | REAR BUMPER SIDE RETAINERS @\$45.90 | 111            |                | \$91.80     |
| 1SET | REAR BUMPER CLIPS                   | 111            | 30.00          | \$48.00     |
| 1PC  | REAR BUMPER SPLASH SHIELD O/S       | 111            |                | \$242.15 X  |
| 1SET | REAR BUMPER SPLASH SHIELD CLIPS O/S | 111            |                | \$30.00 X   |
| 1PC  | REAR END PANEL                      | 306.00         | 415.75         | \$899.15    |
| 1PC  | REAR END PANEL TOP GARNISH          | 111            | 160.00         | \$242.00    |
| 1PC  | REAR END PANEL AIR VENT             | 111            | 75.00          | \$85.00     |
| 2PCS | TAILLAMPS @\$1188.15                | one            | 820 x 2 = 1640 | \$2,376.30  |
| 2PCS | TAILLAMP HOUSING PANELS @\$320.00   | 111            | 150 x 2 = 300  | \$640.00    |
| 1PC  | REAR FENDER O/S                     | 111            |                | \$971.15 X  |
| 2PCS | REAR FENDER INNER TRIMS @\$520.00   | 111            | 345 x 2 = 690  | \$1,040.00  |
| 1SET | REAR FENDER INNER TRIM CLIPS        | 111            |                | \$38.00 X   |
| 1PC  | REAR FLOOR PANEL                    | crumpled / 111 | 705.15         | \$1,340.15  |
| 1PC  | REAR FLOOR PANEL TOP BOARD          | 111            | 345.50         | \$588.20    |
| 1PC  | REAR FLOOR PANEL TOOLS SPONGE       | 111            | 288.50         | \$622.15    |
| 1PC  | REAR EXHAUST                        | 111            |                | \$622.00 X  |
| 2PCS | REAR EXHAUST MOUNTNGS @\$30.00      | 111            |                | \$60.00 X   |
|      |                                     |                |                | \$16,583.80 |

15%

## S.NETT

|     |                            |     |            |
|-----|----------------------------|-----|------------|
| 1PC | REAR WINDSCREEN SEALANT    | 111 | \$50.00 40 |
| 1PC | REAR WINDSCREEN INNER SEAL | 111 | \$50.00 20 |

|  |                               |               |             |      |
|--|-------------------------------|---------------|-------------|------|
| 1PC  | REAR LICENCE PLATE            | 3.11f         | \$50.00     | 40   |
| 1SET   | REAR BUMPER REVERSE SENSOR    | M 01 function | \$280.00    | 200  |
| 1PC  | REAR END PANEL SEALNT         | neu           | \$50.00     | 40   |
| 1SET   | REAR FLOOR PANEL INSULATOR    | 11            | \$200.00    | X    |
| 1PC  | REAR FENDER GLASS SEALANT O/S | 11            | \$50.00     | X    |
| TO CHECK WIRING                              |                               |               | \$50.00     | 20   |
| TO DISMANTLE & REPLACED REAR REVERSE SENSOR  |                               |               | \$80.00     | 30   |
| TO DISMANTLE & REFIX REAR WINDSCREEN         |                               |               | \$150.00    | 120  |
| TO DISMANTLE & REFIX TAILGATE MECHANISM      |                               |               | \$100.00    | 60   |
| TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY |                               |               | \$120.00    | 80   |
| TO DISMANTLE & REFIX REAR EXHAUST            |                               |               | \$100.00    | X    |
| TO DISMANTLE & REFIX REAR FENDER GALSS O/S   |                               |               | \$100.00    | X    |
| TO DISMANTLE & REFIX FUEL TANK               |                               |               | \$100.00    | X    |
| TO SPRAY RUST PROOFING                       |                               |               | \$180.00    | 80   |
| TO MOUNT VEHICLE ON CAR O-LINER              |                               |               | \$380.00    | X    |
| LABOUR FOR PANEL BEATING & REPLACED PARTS    |                               |               | \$2,500.00  | 1200 |
| TO PUTTY & SPRAY PAINTING                    |                               |               | \$2,000.00  | 1200 |
| TOTAL  |                               |               | \$23,173.80 |      |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P-7544.6  
152  
641291  
340  
2790  
954291  
7634