

ASS. REC. BY:

REF:

C9 / T11 24090018/Kap3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 885k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMS 2544 X Yr Regn: 02 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Shuttle c.c. 1496Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 365278 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP7 2002496Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or DavantiFront 8 mmR/Bal. 8 mmL/Bal. 8 mmD.O.A. 29/8/24 D.O.I. 2/9/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/19/21 Rm 8:3000t. Colw Used #11913.52, 70%

Date/Time, File Pass to?

1) 09/19/21 Rm

Date/Time, File Return to?

2)

☐ : Prel. Report☐ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + RS. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.A. (\$) 5000

MER-TP



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 31/08/24
VEHICLE : SMS2654X
MAKE/MODEL : HONDA SHUTTLE
CHASSIS NO : GP7-2002496
MILLAGE : 365200KM
TYRE SIZE :
DOA : 29/08/24

Not Authored
L1 Pay & 5000/-
Penny After Pain
5 days

List items

01 PC	REAR BUMPER	1050.60	Bu	\$	2,291.40	✓
01 PC	REAR RH BUMPER REFLECTOR GANISH			\$	177.36	X
01 PC	REAR RH BUMPER REFLECTOR		SL	\$	163.20	X
01 PC	REAR BUMPER TOWING COVER		SL	\$	42.84	X
02 PC	REAR BUMPER SIDE RETAINER @ \$121.95	064	CLSDIT	\$	243.90	✓
01 PC	REAR BUMPER RH INNER SIDE PROTECTOR			\$	65.28	X
01 PC	REAR BUMPER MOULDING		NJP	\$	219.60	X
01 PC	REAR BUMPER INNER BRACKET			\$	60.06	X
01 PC	REAR END PANEL	681.20		\$	854.30	✓
01 PC	REAR END PANEL TOP GANISH			\$	236.10	✓
01 PC	REAR TAIL GATE WEATERSTRIP	166.50	Dis/Mod	\$	299.46	506in 83-105N
01 PC	REAR TAIL GATE	1193.20	Bu	\$	2,522.22	✓
01 PC	REAR TAIL GATE OUTER GANISH			\$	387.85	X
01 PC	REAR TAIL GATE OUTER CHROME GANISH		CM	\$	286.30	✓
01 PC	REAR TAIL GATE EMBLEM 'LOGO'	98.40	CM	\$	125.70	✓
01 PC	REAR TAIL GATE EMBLEM 'SHUTTLE'	92.50	CM	\$	145.20	✓
01 PC	REAR TAIL GATE EMBLEM 'HYBIRD'	94.30	CM	\$	105.60	✓
01 PC	REAR TAIL GATE OUTER HANDLE		SL	\$	165.40	X
02 PC	REAR TAIL GATE NUMBER PLATE LAMP @ \$98.40		SL	\$	196.80	X
01 PC	REAR RH TAIL LAMP	592.30	CM	\$	943.05	✓
01 PC	REAR RH TAIL GATE LAMP	580.90	CM	\$	891.08	✓
01 PC	REAR TAIL GATE INNER TRIM BOARD	310.60	Bu/Mod	\$	781.60	✓
01 PC	REAR WIPER MOTOR		SL	\$	732.60	X
02 PC	REAR TAIL GATE ABSORBER @ \$299.46		SL	\$	598.92	X
01 PC	REAR TAIL GATE INNER LOCK		\$	R	456.85	X
01 PC	REAR TAIL GATE CATCH LOCK		\$	R	96.30	X
01 PC	REAR TAIL GATE INNER HANDLE		\$	SL	93.35	X
02 PC	REAR TAIL GATE STOPPER @ \$25.00		\$	SL	50.00	X
TOTAL PARTS COST		019C Fender inner trim board. RH Rear.			\$ 13,232.32	✓
		mgcm 8489.00				✓

Special Nett Item:

10 PC	DOOR TRIM BOARD CLIP @ \$8.00	CM	\$	80.00	✓
02 PC	PARKING SENSOR @ \$250.00		\$	500.00	X
01 PC	REAR PARKING CAMERA	SL	\$	520.00	X
05 PC	REAR BUMPER CLIP @ \$8.00	\$CM	\$	40.00	✓
01 PC	WINDSCREEN SEALANT	CM	\$	100.00	405N
			\$	1,240.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	800.00	✓
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$	600.00	✓
3. TO SUPPLY LABOUR TO DISMANTLE & REFIT REAR WINDSCREEN	\$	300.00	120L
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$	100.00	20L
5. TO SUPPLY COMPUTER DIANOGTIC	\$	250.00	X
	\$	2,050.00	

TOTAL PARTS

SPECIAL NETT ITEM

TOTAL LABOUR

TOTAL COST OF REPAIR

\$ 13,232.32
\$ 1,240.00
\$ 2,050.00
\$ 16,522.32



MOTORSPORTS

JD MOTORSPORTS PTE LTD
25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 31/08/24
VEHICLE : SMS2654X
MAKE/MODEL : HONDA SHUTTLE
CHASSIS NO : GP7-2002496
MILLAGE : 365200KM
TYRE SIZE :
DOA : 29/08/24

Not Authored
L1 Pay &
Recovery After Paint
4-5 days

List items

01 PC	REAR BUMPER
01 PC	REAR RH BUMPER REFLECTOR GANISH
01 PC	REAR RH BUMPER REFLECTOR
01 PC	REAR BUMPER TOWING COVER
02 PC	REAR BUMPER SIDE RETAINER @ \$121.95
01 PC	REAR BUMPER RH INNER SIDE PROTECTOR
01 PC	REAR BUMPER MOULDING
01 PC	REAR BUMPER INNER BRACKET
01 PC	REAR END PANEL
01 PC	REAR END PANEL TOP GANISH
01 PC	REAR TAIL GATE WEATERSTRIP
01 PC	REAR TAIL GATE
01 PC	REAR TAIL GATE OUTER GANISH
01 PC	REAR TAIL GATE OUTER CHROME GANISH
01 PC	REAR TAIL GATE EMBLEM 'LOGO'
01 PC	REAR TAIL GATE EMBLEM 'SHUTTLE'
01 PC	REAR TAIL GATE EMBLEM 'HYBIRD'
01 PC	REAR TAIL GATE OUTER HANDLE
02 PC	REAR TAIL GATE NUMBER PLATE LAMP @ \$98.40
01 PC	REAR RH TAIL LAMP
01 PC	REAR RH TAIL GATE LAMP
01 PC	REAR TAIL GATE INNER TRIM BOARD
01 PC	REAR WIPER MOTOR
02 PC	REAR TAIL GATE ABSORBER @ \$299.46
01 PC	REAR TAIL GATE INNER LOCK
01 PC	REAR TAIL GATE CATCH LOCK
01 PC	REAR TAIL GATE INNER HANDLE
02 PC	REAR TAIL GATE STOPPER @ \$25.00

TOTAL PARTS COST

Re	\$	2,291.40	✓
Sn	\$	177.36	X
Sn	\$	163.20	X
Sn	\$	42.84	X
CLSDI	\$	243.90	LT
Sn	\$	65.28	X
NJP	\$	219.60	X
R	\$	60.06	X
B	\$	854.30	✓
Od	\$	236.10	✓
Dij/M	\$	299.46	50% in
R	\$	2,522.22	✓
Sn	\$	387.85	X
CMS	\$	286.30	✓
M	\$	125.70	✓
M	\$	145.20	✓
M	\$	105.60	✓
Sn	\$	165.40	X
Sn	\$	196.80	X
CMS	\$	943.05	✓
CMS	\$	891.08	✓
Sn	\$	781.60	X
Sn	\$	732.60	X
Sn	\$	598.92	X
R	\$	456.85	X
R	\$	96.30	X
Sn	\$	93.35	X
Sn	\$	50.00	X
	\$	<u>13,232.32</u>	

Rear RH Bumper ganish &

Special Nett Item:

10 PC	DOOR TRIM BOARD CLIP @ \$8.00
02 PC	PARKING SENSOR @ \$250.00
01 PC	REAR PARKING CAMERA
05 PC	REAR BUMPER CLIP @ \$8.00
01 PC	WINDSCREEN SEALANT

M	\$	80.00	✓
Sn	\$	500.00	X
Sn	\$	520.00	X
Sn	\$	40.00	✓
M	\$	100.00	40% in
	\$	<u>1,240.00</u>	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO DISMANTLE & REFIT REAR WINDSCREEN
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
5. TO SUPPLY COMPUTER DIANOGIC

\$	800.00	✓
\$	600.00	✓
\$	300.00	120%
\$	100.00	20%
sun	250.00	X
\$	<u>2,050.00</u>	

TOTAL PARTS
SPECIAL NETT ITEM
TOTAL LABOUR
TOTAL COST OF REPAIR

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	13,232.32
\$	1,240.00
\$	2,050.00
\$	<u>16,522.32</u>