

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Tan Jinng Yi
Blk 190 Canberra Drive
07 - 41
Singapore 767957

Vehicle No : SMX 2889 J
Make : Hyundai Avante
Year :

Fax : 64816131

Not withair
11 Lmp @ 5700k
Presury After Pain
5 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear boot lid	✓
1 pc	Rear windscreen moulding	✓
1 pc	Rear boot lid inner lock	? photo
1 pc	Rear boot lid emblem " Logo	✓
1 pc	Rear boot lid emblem " AVANTE "	✓
1 pc	Rear boot lid top cover	✓
1 pc	Rear boot lid reflector	? photo
2 pcs	Rear tail-lamp assy	✓
1 pc	Rear boot rubber	? photo
1 pc	Rear end panel	? photo
1 pc	Rear end panel inner garnish	
1 pc	Rear n/s fender inner trim board	reuse
1 pc	Rear bumper	✓
1 pc	Rear bumper lower garnish	✓ 341
1 pc	Rear bumper side retainer	✓
2 pcs	Rear bumper reinforcement	? photo 394.80
1 pc	Rear n/s collision corner sensor modern	? photo
1 pc	Rear n/s bumper reflector	? photo
2 pcs	Rear reverse sensor	photo
1 pc	Rear reverse camera	reuse

Bu	\$2,073.00	✓
re	\$115.00	✓
nd	\$185.00	✓
re	\$65.00	✓
re	\$75.00	✓
su	\$499.00	✓
cm	\$1,052.00	✓
su	\$875.00	✓
nd/10/1	\$1,750.00	✓
	\$165.00	✓
Bu	\$485.00	✓
su	\$184.00	✓
su	\$311.00	✓
Bu	\$499.00	✓
nd/10/1	\$394.00	✓
\$75.00	\$150.00	✓
cm	\$465.00	✓
cm	\$1,189.00	✓
su	\$95.00	✓
nd/10/1	\$370.00	✓
\$185.00	\$826.00	✓
	\$10,947.00	
Less 20 %	\$2,189.40	
	\$8,757.60	

S. Nett Item

1 pc	Rear no plate
20 pcs	Clips

	nd	\$40.00	✓
\$2.00	re	\$40.00	✓

Labour Charges

Remove/renew the above parts. Cut out & reweld rear end panel, knock out & reshape

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

rear spare tyre panel, rear fender, tail-lamp panel etc.

To putty & spray paint on rear accident affected portion.

Check/reconnect wiring.

Remove/refit rear windscreen

Diagnostic check and remove/renew rear collision corner sensor & reset same

\$1,200.00 *600*

\$1,200.00 *600*

\$40.00 *200*

\$120.00 *✓*

\$280.00 *1200*

Total

\$11,677.60