

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K



8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com

Xiao Chun

DATE : 18.06.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLZ6475U**
MODEL : **HONDA VEZEL**
DATE OF ACCIDENT : 18.06.2024
TIME OF ACCIDENT : 09:00 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	HEADLAMP RH <i>cracked</i>	1	\$ 1,152.30	\$ 1,152.30
2	HEADLAMP LOWER BRACKET RH <i>new</i>	1	\$ 52.00	\$ 52.00
3	HEADLAMP SIDE BRACKET RH <i>new</i>	1	\$ 55.00	\$ 55.00
4	FRONT BUMPER <i>dent</i>	1	\$ 878.50	\$ 878.50
5	FRONT BUMPER LOWER LIP <i>crack</i>	1	\$ 355.00	\$ 355.00
6	FRONT BUMPER FOGLAMP RH <i>new</i>	1	\$ 327.70	\$ 327.70
7	FRONT BUMPER FOGLAMP COVER RH <i>cracked</i>	1	\$ 69.00	\$ 69.00
8	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 150.00	\$ 150.00
9	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 23.00	\$ 46.00
10	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 321.00	\$ 321.00
11	CENTRE GRILLE	1	\$ 332.50	\$ 332.50
12	GRILLE LOGO	1	\$ 28.00	\$ 28.00
13	GRILLE COVER GARNISH	1	\$ 285.00	\$ 285.00
14	FRONT FENDER RH <i>dent</i>	1	\$ 748.80	\$ 748.80
15	FRONT FENDER EMBLE 'HYBRID' RH <i>new</i>	1	\$ 85.30	\$ 748.80
16	FRONT FENDER INNER GARNISH RH <i>new</i>	1	\$ 85.00	\$ 85.00
17	FRONT FENDER ARCD GARNISH RH <i>new</i>	1	\$ 195.00	\$ 195.00
18	FRONT FENDER INNER COWLING RH <i>new</i>	1	\$ 170.50	\$ 170.50
19	FRONT WHEEL RIM RH <i>new</i>	1	\$ 1,450.00	\$ 1,450.00
20	FRONT ABS SENSOR	1	\$ 295.00	\$ 295.00
21	FRONT STEERING RACK & PINION	1	\$ 1,750.00	\$ 1,750.00
22	FRONT SHOCK ABSORBER RH	1	\$ 586.50	\$ 586.50

Handwritten notes and calculations:
 745
 582
 85.30
 400(SN)

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLZ6475U**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 18.06.2024
 TIME OF ACCIDENT : 09:00 HOURS

23	FRONT LOWER ARM RH	1	\$ 474.70	\$ 474.70
24	FRONT KNUCKLE ARM RH	1	\$ 461.70	\$ 461.70
25	FRONT KNUCKLE ARM INNER BEARING RH	1	\$ 262.00	\$ 262.00
26	FRONT WHEEL HUP RH	1	\$ 379.40	\$ 379.40
27	FRONT LINKAGE RH	1	\$ 65.00	\$ 65.00

S.N: 400 3183.60
 2546.88

TOTAL PRICE \$ 11,724.40
 LESS 20% \$ 2,344.88
SUB TOTAL PRICE \$ 9,379.52

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
2	FRONT BUMPER LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
3	FRONT WIPER PANEL GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
4	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
5	FRONT FENDER INNER GARNISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
6	FRONT FENDER ARCED GARNISH CLIP LH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
7	FRONT FENDER INNER COWLING CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
8	SIDE SKIRT CLIP RH <i>new</i>	1	\$ 80.00	\$ 80.00
9	WHEEL CAP (SET) <i>new</i>	1	\$ 150.00	\$ 150.00
10	FRONT WHEEL TYRE RH <i>2 new</i>	1	\$ 450.00	\$ 450.00
11	FRONT WHEEL RIM RH <i>Repeinted</i>	1	\$ 1,500.00	\$ 1,500.00
12	BRAKE OIL <i>new</i>	1	\$ 40.00	\$ 40.00

80

TOTAL \$ 2,550.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	400
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	400
3	TUFF COAT	\$ 250.00	X
4	WIRING CHECK	\$ 120.00	30

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLZ6475U**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 18.06.2024
 TIME OF ACCIDENT : 09:00 HOURS

5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	+
10	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	+
11	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	+
12	FOUR WHEEL ALIGNMENT	\$ 120.00	80
17	RESET ABS LIGHT	\$ 350.00	x
18	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	+

910

TOTAL \$ 7,220.00

TOTAL PARTS COST : \$ 11,929.52
 TOTAL LABOUR COST : \$ 7,220.00
 TOTAL REPAIR COST : \$ 19,149.52

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Adrian Lim
 L/S 19/06/24

04 Days

total: 3936.88
 L/S: 3150

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: