

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24090020/TVP3E2**Date:** 25/09/2024**REFERENCE**

Insured/Claimant:	AFIQ ASYRANI BIN AZHAR	Policy No:	MPC24B00058000	
Date of Loss:	29/08/2024	Nature of Claim:	OD	Claim No: DMPC2401140H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH2640E		
Make & Model:	BMW 216D, 1.5 D GRAN TOURER LED NAV 7 SEATER (A)	Engine No:	31729664B37C15A
Reg. Date:	28/10/2016 (Man. Year: 2016)	Chassis No:	WBA2E320005B45440
Colour:	White	Odometer:	0 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$48,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
- Excess (\$\$)	0.00	600.00	-600.00	
Nett Amount (\$\$)	0.00	-600.00	600.00	

INSPECTION

Date of Assignment:	02/09/2024	Present Location:	Century Motors (Singapore) Pte Ltd (HQ)
Date Inspected:	03/09/2024	Inspected At:	Century Motors (Singapore) Pte Ltd (HQ) 6 Marsiling Lane, Singapore 739145
Estimated Period of Repair:	0.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value :	\$48,000.00
OMV :	\$31,478.00
PARF Rebate (1) :	\$15,642.00
Quota Premium Paid :	\$50,991.00
COE Rebate (2) :	\$10,965.00
Total Rebate (1) + (2) = :	\$26,607.00

The total amount incurred will be Market Value \$48,000.00 minus Total Rebate \$26,607.00 = \$21,393.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2024)
Parts:	M1-MPV	BMW 216D 1.5 D GRAN TOURER LED NAV 7 SEATER (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH2640E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >