



Your Ref : DMPC2401140H/CT

Date: 25th Sep 2024

Our Ref : CS/ICS24090020/Tvp3e2

M/s ECICS Ltd

10 Eunos Road 8

Singapore Post Centre #09-04A

Singapore 408600

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLH 2640E
ACCIDENT ON 29/08/2024**

Instruction was received to inspect the vehicle Reg. No. SLH 2640E. The inspection was conducted on 29/08/2024 at the premises of M/s Century Motors (Singapore) Pte Ltd, 6 Marsiling, Singapore 739145.

The following vehicle information was recorded:

Registration Number	: SLH 2640E
Make/Model	: B.M.W. 216D Gran Tourer Led Nav 7 Seater
Year of Registration	: 2016
Body Colour	: White
Chassis Number	: WBA2E320005B45440
Engine Capacity	: 1496 cc

The vehicle caught fire. The cause of fire probably due to short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 48,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 26,607.00)
Nett Liability	<u>S\$ 21,393.00</u> =====

Vehicle Inspected By:



MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.