



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS ALLIED WORLD ASSURANCE COMPANY LTD
(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8TH FLOOR)
MAPLETREE ANSON SINGAPORE 079914

Ref: CS/AWA24090023/Rqp3e2

Date: 02/09/2024

Code: AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNS 8377U	Veh. Inspected	SLS 5205B
Policy No.	BVFPSB0009212401	Coverage	0
Claim No.	SNS8377/SG	Excess	\$0.00
Assign From	HEW LEE FONG	Assign Date	02/09/2024

2. Vehicle Details

Make & Model	MAZDA 3 SEDAN 1.5 AT S/R	C.C	1496
Engine No.	P520451568	Year of Reg.	27/09/2017
Chassis No.	JM6BN22A8H0158959	Colour	GREY
Odometer	1496 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60 R16	LAUFENN	6
L/H Front Tyre	205/60 R16	LAUFENN	6
R/H Rear Tyre	205/60 R16	LAUFENN	6
L/H Rear Tyre	205/60 R16	LAUFENN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/08/2024	Inspection Date	05/09/2024
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD - 74 KIAN TECK ROAD SINGAPORE 628800		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days