

E M Solution Pte Ltd

160 Sin Ming Drive #03-19, Sin Ming Autocity
Singapore 575722
Tel: 64560226
GST/Reg. No: 201016308K

NOT WITHHOLD
1/1 By @ 2050p
Putty After Rain
2 days

ESTIMATE

Date : 2nd Sept 2024

Mdm Tay Kim Wah
Blk 337 Bukit Batok St 34, #08-02
Singapore 650337

Veh No : SJR 7537J
Make/Model : Toyota Estima
Chassis No : ACR507004060
Date of Acc : 20.08.24
TP Veh No : SLJ 1188R

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Frt Bumper 960	Bur/Net	1,917.80 ✓
2	1 pc	Frt Bumper Side Retainer LH	\$ 164.80	164.80 X
3	1 pc	Headlamp LH	my.com	1,917.80 ✓
			\$	4,000.40
			Less 25%	\$ 1,000.10
				\$ 3,000.30
4	1 set	Frt Bumper Clips	S/Nett	\$ 50.00
			Parts Total :	\$ 3,050.30
Labour				
1		To remove & rearrange electrical wirings, check lightings		\$ 80.00 2d
2		To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.		\$ 400.00 200d
3		Putty and respray painting on affected portions.		\$ 400.00 220d
4		Rust proofing on affected portions.		\$ 80.00 X
			Labour Total :	\$ 960.00
			Total Parts & Labour :	\$ 4,010.30


for E M Solution Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: