

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

Not Authorized

mercus

3/9/24

5 days 2/5 \$ 10,000

2 September 2024

REG NO. : SCJ 2808 K
MAKE/MODEL : MERCEDES BENZ E200

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front headlamp -LH <i>n7</i>	\$ 2,695.00 X
1	Front bumper <i>cur/Torn</i>	\$ 1,755.21 2,198.00 ✓
1	Front bumper fog lamp <i>n7</i>	\$ 325.00 X
1	Front bumper fog lamp cover <i>n7</i>	\$ 185.00 X
1	Front bumper inner sponge <i>n7</i>	\$ 165.00 X
1	Front bumper reinforcement <i>n7</i>	\$ 596.00 X
1	Front bumper side retainer <i>Che</i>	\$ 75.00 ✓
1	Front bumper chrome moulding <i>n7</i>	\$ 125.00 ✓
2	Front bumper side PDC sensors <i>n7</i>	\$ 710.00 X
1	Front bumper side undercover <i>n7</i>	\$ 355.00 X
1	Front fender -LH <i>D.S</i>	\$ 1212.35 1,550.00 ✓
1	Front fender inner shield <i>Torn</i>	\$ 175.00 ✓
1	Front fender side protector <i>B20</i>	\$ 85.00 ✓
1	Front wheel rim -LH <i>waped/surf</i>	\$ 2,880.00 600 S/W
1	Front wheel hub with bearing <i>Daye</i>	\$ 587.54 ✓
1	Front shock absorber <i>SL</i>	\$ 727.78 X
1	Front knuckle arm	\$ 1,027.09 ✓
1	Front lower arm <i>Surf</i>	\$ 1,038.00 ✓
1	Front top arm <i>n7</i>	\$ 479.20 X
1	Front control arm <i>n7</i>	\$ 437.00 X
1	Stabilizer bar link <i>n7</i>	\$ 97.10 X
1	Front door -LH <i>Tw/cu</i>	\$ 2980.00 3,126.00 ✓
1	Front door checker <i>Tw</i>	\$ 155.00 ✓
2	Front door hinges <i>n7</i>	\$ 330.00 X
1	Front door inner board <i>n7</i>	\$ 1,000.00 X
1	Front door lock <i>n7</i>	\$ 435.00 X
1	Front door chrome protector <i>Surf</i>	\$ 165.00 ✓
1	Front door protector <i>Surf</i>	\$ 225.00 ✓
1	Front door side mirror <i>Daye/cu</i>	\$ 758.00 ✓
1 <i>Surf</i>	Front door weatherstrip <i>n7</i>	\$ 295.00 ✓
1	Rocker panel <i>n</i>	\$ 995.00 X
1	Rocker panel outer garnish <i>cur/Torn</i>	\$ 655.00 ✓
		\$ 24,651.71
	Less 5%	\$ 1,232.59
		\$ 23,419.12

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	111	\$	80.00	40
1	Front fender inner shield clip (1 set)	111	\$	60.00	40
1	Front tyre	511	\$	650.00	X
			\$	790.00	

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.		\$	80.00	20
2	To remove and refit inner garnishes.	11	\$	150.00	X
3	To remove and refit front sensor.		\$	200.00	30
4	To remove and refit front undercarriage.		\$	250.00	150
5	To conduct wheel alignment.		\$	150.00	80
6	To remove, refit door fittings and replace damaged parts, transfer all fittings		\$	200.00	60
7	To apply undercoating.		\$	200.00	50
8	Panel beating.		\$	2,000.00	500
9	To re-spray painting on the affected areas.		\$	1,800.00	900
			\$	5,030.00	

GRAND TOTAL :

\$ 29,239.12

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

R. 11313-19
102
10181-87
680