

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
IOB Building #04-05
Singapore 049711

Tel: 63476100 Fax: 62244174 , 62257743
Attn: Motor Claim Department \ INDIA
INTERNATIONAL

Your Ref No: TP 0824-8217
Claim Type: Third Party
Accident Date: 29 August 2024
TP Veh Reg No: PC6327M

Estimate No: **EST1511722**
Date: 30 Aug 2024
Policy No: P11054548R00
Veh Reg No: SLX6342E
Make/Model: HONDA SHUTTLE 1.5G
CVT
Chassis No: GK81200381
Engine No: L15B5460447
Reg. Date: 02 Apr 2018

Estimate Repair Cost to Vehicle No: SLX6342E

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 SIDE MIRROR ASSY - RH	573.30	1 PC	573.30	
2 SIDE MIRROR OUTER COVER - RH	60.30	1 PC	60.30	
			633.60	
		Less 20%	-126.72	506.88
Labour				
3 TO REPLACE SIDE MIRROR	150.00	1 PC	150.00	
4 TO RESPRAY PAINT ON SIDE MIRROR COVER	120.00	1 PC	120.00	
5 TO CHECK WIRING	30.00	1 PC	30.00	
				300.00

Total 806.88
Add GST @ 9% 72.62
Total Amount Payable SGD 879.50

SINGAPORE DOLLAR EIGHT HUNDRED SEVENTY NINE AND CENTS FIFTY ONLY

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) before resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE