

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090027/EPA3Q2
Date: 12/11/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MPC0000943_04
Claimant Vehicle No : FBM3640R Insured Vehicle No : SLL2096E
Date of Loss: 28/08/2024 Nature of Claim: TP Claim No: MPC2024D0010119

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBM3640R
Make & Model: YAMAHA MTN155, 155cc Engine No: G3S6E0012966
Reg. Date: 27/06/2023 (Man. Year: 2022) Chassis No: MH3RG478000001385
Colour: Silver Odometer: 18409 km
Engine Capacity: 155 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70-17 Rear Tyre Size: 140/70-17
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,373.00	2,133.70	239.30	10.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	450.00	300.00	150.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,823.00	2,433.70	389.30	13.79
+ GST 9.00/9.00% (S\$)	254.07	219.03	35.04	13.79
Nett Amount (S\$)	3,077.07	2,652.73	424.34	13.79
+ Loss of Use (3.0 x S\$25.00/day) (S\$)		75.00		
Nett Liability (S\$)		2,727.73		

INSPECTION

Date of Assignment: 29/08/2024
Date Inspected: 29/08/2024 Inspected At: Atan Motoring Supply Pte Ltd (HQ)
Block 3006 Ubi Road 1, #01-368/370
Singapore 408700
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Oct 2024)	
Parts:	N/A	YAMAHA MTN155 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM3640R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front Fork Complete	Bent	1,100.00 F	*1,100.00 FL
2	1		*Head Lamp Bracket	Bent/ Cut	75.00 F	*75.00 FL
3	1		*Handle Bar	Bent	65.00 F	*65.00 FL
4	1		*Brake Lever	Cut	18.00 F	*18.00 FL
5	1		*Balancer	Cut	16.00 F	*16.00 FL
6	1		*Brake Pedal	Bent	45.00 F	*45.00 FL
7	1		*Foot Rest (FR)	Cut	16.00 F	*16.00 FL
8	1		*Exhaust Protector Front	Cut	45.00 F	*45.00 FL
9	1		*Exhaust Protector Rear	Cut	40.00 F	*40.00 FL
10	1		*Tank Cover Left	Deformed	85.00 F	*85.00 FL
11	1		*Tank Cover Right	Cut	85.00 F	*85.00 FL
12	1		*Front Brake Disc	Bent	65.00 F	*65.00 FL
13	1		*Front Brake Calliper	Bent/ Cut	120.00 F	*120.00 FL
14	1		*Front Rim Shaft	Bent	18.00 F	*18.00 FL
15	1		*Rim	Bent	300.00 F	*300.00 FL
16	1		*Box & Bracket	Bent	280.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,373.00	2,343.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	209.30
Total Parts (\$)	2,373.00	2,133.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Labour Charges	New	450.00	300.00
Gross Labour Cost (\$\$)			450.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >