

ASS. REC. BY:

REF:

C711

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SGR 66865

Yr Regn:

10.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS

X-Trail

c.c

Wagon

1997

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

189211

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JNITANT 328 0010345

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

225/55R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

31/8/24

D.O.I.

31/9/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



MOTORSPORTS

Veh no : SGF 6686 S

Model : Nissan X-Trial

Chassis No : JN1JANT32Z0010345

Milage : 189211

D.O.A : 31/08/2024

List Item :

Not Authorized

1/1/2024

*Presumy After Repair
4 days*

01ps Front bumper	CM	\$ 1519.84	✓
02ps Front bumper bracket @ \$ 42 x 2	S	84.00	
02ps Front bumper side retainer @ \$ 65 x 2	nit / pu	\$ 130.00	✓
01ps Front bumper lower cover		\$ 700.20	?
01ps Front bumper lower grill		\$ 220.36	?
01ps Front bumper lower garnish(CHROME)	nd	\$ 154.04	✓
01ps Front bumper reinforcement		\$ 539.56	?
01ps Front bumper sponge		\$ 347.68	?
06ps Front bumper clip @ \$ 8 x 6	nd	\$ 48.00	✓
01ps Front bumper towing cover	nit	\$ 48.40	✓
02ps Front bumper fog lamp cover @ \$ 103.80 x 2	nd / pu	\$ 207.60	✓
02ps Front bumper fog lamp @ \$ 695.04 x 2	R	\$ 1390.08	X
02ps Front bumper fog lamp bracket @ 73.60 x 2		\$ 147.20	?
01ps Front grill base	CM	\$ 385.30	✓
01ps Front grill chrome moulding	CM	\$ 223.15	✓
01ps Front grill emblem	nd	\$ 65.80	✓
08ps Front grill	CM	\$ 262.00	✓
01ps Front support panel (TOP)	R	\$ 387.60	X
01ps Front support panel (LOWER)	R	\$ 617.88	X



MOTORSPORTS



01ps Front support side panel			K	\$ 79.36	X
02ps Front support panel side garnish @ \$ 123.56 x 2				\$ 247.12	7
01ps a/c condenser				\$ 2419.80	7
01ps Auto cooler			Sm	\$ 663.12	X
01ps Outside temp sensor				\$ 87.00	7
01ps a/c pipe (Pressure hose)			R	\$ 270.20	X
01ps Radiator				\$ 2891.44	7
01ps Radiator garnish (Side)			Sm	\$ 72.92	X
01ps Radiator garnish (lower)				\$ 170.12	7
02ps front headlamp @ \$ 3432.20 x 2	old mgc m	NIS7		\$ 6864.40	4
02ps Front headlamp lower bracket @ \$ 156.92 x 2				\$ 313.84	7
01ps Front bonnet			K	\$ 1013.20	X
01ps Front bonnet insulator			Sm	\$ 287.48	X
02ps Front bonnet hinges @ \$ 83.20 x 2			K	\$ 166.40	X
01ps Front bonnet lock			K	\$ 182.04	X
01ps Front bonnet lock cable			Sm	\$ 98.84	X
02ps Front fender @ \$ 910.96 x 2			K	\$ 1821.92	X
02ps Front fender inner cowling @ \$ 196.48 x 2			Sm	\$ 392.96	X
12ps Front fender inner cowling clip @ \$ 8 x 12			Sm	\$ 96.00	X

Total : \$

Less 10 % \$



MOTORSPORTS

Special nett item :

01ps Front number plate

01ps Front number plate garnish

01ps Front number plate base

01ps Front collision sensor

01ps Front camera

23 \$ 25 SN }
\$ 30 SN } 45 SN

001 \$ 185 SN ✓

\$ 365 SN 7

\$ 580 SN 7

Total : \$ 1185 SN

Labour:

- 01) To supply labour & Parts to replace and repair above mentioned parts : \$ 1000 500
02) To supply Labour & Paints to spray accident affected area : \$ 1200 600
03) To supply labour & gas to refill a/c condenser gas : \$ 150 7
04) To supply labour to re-wire replace parts : \$ 120 201
05) To supply labour to straighten chassis frame ~ ~ : \$ 300 X
06) To supply labour to conduct computer dynostic : \$ 200 7

Total ; \$ 2970

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance company

Acknowledged by repairer

Signature:

Date: