

ASS. REC. BY:

REF:

C7124090029/Kah3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1) 10/9/2017

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

F. Extras

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / LB.I. (\$

EZ claims Tp

6950



MOTORSPORTS

Veh no : SGF 6686 S

Model : Nissan X-Trial

Chassis No : JN1JANT32Z0010345

Milage : 189211

D.O.A : 31/08/2024

List Item :

Not Authorize
1/1 Day @ 6950/-
Resurvey After Poring
4 days

01ps Front bumper	945.20	CM	\$ 1519.84	✓
02ps Front bumper bracket @ \$ 42 x 2		R S	84.00	X
02ps Front bumper side retainer @ \$ 65 x 2		nit / ps	\$ 130.00	✓
01ps Front bumper lower cover	321.	CM	\$ 700.20	✓
01ps Front bumper lower grill		CM	\$ 220.36	✓
01ps Front bumper lower garnish(CHROME)		nd	\$ 154.04	✓
01ps Front bumper reinforcement		R	\$ 539.56	X
01ps Front bumper sponge	240	CM	\$ 347.68	✓
06ps Front bumper clip @ \$ 8 x 6		na	\$ 48.00	✓
01ps Front bumper towing cover		nit	\$ 48.40	✓
02ps Front bumper fog lamp cover @ \$ 103.80 x 2		nd / Gt	\$ 207.60	✓
02ps Front bumper fog lamp @ \$ 695.04 x 2		R	\$ 1390.08	X
02ps Front bumper fog lamp bracket @ 73.60 x 2		R	\$ 147.20	X
01ps Front grill base		CM	\$ 385.30	✓
01ps Front grill chrome moulding		CM	\$ 223.15	✓
01ps Front grill emblem		na	\$ 65.80	✓
08ps Front grill		CM	\$ 262.00	✓
01ps Front support panel (TOP)		R	\$ 387.60	X
01ps Front support panel (LOWER)		R	\$ 617.88	X



MOTORSPORTS



01ps Front support side panel

N \$ 79.36 *X*

02ps Front support panel side garnish @ \$ 123.56 x 2

o/s od \$ 247.12 *2X*

01ps a/c condenser

Sm \$ 2419.80 *X*

01ps Auto cooler

Sm \$ 663.12 *X*

01ps Outside temp sensor

Sm \$ 87.00 *X*

01ps a/c pipe (Pressure hose)

Sm \$ 270.20 *X*

01ps Radiator

Sm \$ 2891.44 *X*

01ps Radiator garnish (Side)

Sm \$ 72.92 *X*

01ps Radiator garnish (lower)

o/s \$ 170.12 *2*

02ps front headlamp @ \$ 3432.20 x 2 *o/s 2115-30 o/s mg/cm*

N/S mg/cm \$ 6864.40 *4X*

02ps Front headlamp lower bracket @ \$ 156.92 x 2

N \$ 313.84 *X*

01ps Front bonnet

N \$ 1013.20 *X*

01ps Front bonnet insulator

Sm \$ 287.48 *X*

02ps Front bonnet hinges @ \$ 83.20 x 2

N \$ 166.40 *X*

01ps Front bonnet lock

N \$ 182.04 *X*

01ps Front bonnet lock cable

Sm \$ 98.84 *X*

02ps Front fender @ \$ 910.96 x 2

N \$ 1821.92 *X*

02ps Front fender inner cowling @ \$ 196.48 x 2

Sm \$ 392.96 *X*

12ps Front fender inner cowling clip @ \$ 8 x 12

N \$ 96.00 *X*

Total : \$

Less 10 % \$



MOTORSPORTS

Special nett item :

01ps Front number plate

01ps Front number plate garnish

01ps Front number plate base

01ps Front collision sensor

01ps Front camera

Bz \$ 25 SN }
\$ 30 SN } 45sn
Dd \$ 185 SN ✓
Dd \$ 365 SN ✓
Bm \$ 580 SN X

Total : \$ 1185 SN

Labour:

- 01) To supply labour & Parts to replace and repair above mentioned parts
- 02) To supply Labour & Paints to spray accident affected area
- 03) To supply labour & gas to refill a/c condenser gas
- 04) To supply labour to re-wire replace parts
- 05) To supply labour to straighten chassis frame
- 06) To supply labour to conduct computer dynostic

: \$ 1000 500d
: \$ 1200 60d
nn: \$ 150 X
: \$ 120 201
nn : \$ 300 X
nn: \$ 200 X

Total ; \$ 2970

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date