

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

AIG

Owner : Lee Chee Meng (82282180)

Accident Date : 20-Aug-24

Vehicle No : FBP4247X(COE : 300519-290529)

Vehicle Model : Yamaha Sniper T150

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Front fork tube assy	\$ 320.00 640.00 ✓
1	Fork under bracket	\$ 220.00 ✓
1	Front wheel rim	\$ 485.00 X
1	Front rim shaft	\$ 105.00 X
1	Front rim bearing	\$ 88.00 X
1	Front brake disc	\$ 185.00 X
1	Handle-bar	155 \$ 320.00 280.00 ✓
1	Handle-bar end	38 \$ 120.00
1	Hand grip (1 set)	\$ 98.00 X
1	Head Lamp	\$ 485.00
1	Head Lamp Cover	125 \$ 135.00
1	Side mirror - 1 set	\$ 128.00 X
1	Clutch lever	60 \$ 105.00
1	Front signal - 1 set	80 \$ 160.00
1	Pilot light	\$ 380.00 X
1	Horn inner panel	\$ 150.00 ✓
1	Front inner cover	160 \$ 190.00
1	Fairing assy (1 set)	550 \$ 680.00 ✓
1	Front footrest bracket	\$ 216.00 X
2	Front footrest	60 n/s \$ 158.00 120.00
1	Gear pedal	\$ 135.00 X
2	Rear footrest	\$ 150.00 X
2	Reat footrest bracket	\$ 360.00 X
		\$ 5,653.00
Less 10%		\$ 565.30
		\$ 5,087.70

Special Net Items

1	Number plate (1 set)	\$ 38.00 X
2	Fork oils	\$ 30.00 X
2	Fork oil seals	\$ 56.00 ✓
1	Steering cone (1 set)	\$ 90.00 60
1	Sticker (1 set)	\$ 120.00 60
1	Rear box	\$ 480.00 300
1	Rear box bracket	\$ 180.00 X
		\$ 994.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Lee Chee Meng (82282180)

Accident Date : 20-Aug-24

Vehicle No : **FBP4247X**(COE : 300519-290529)

Vehicle Model : Yamaha Sniper T150

Estimated Repair Costs

S/No.	Labour	
1	To ckeck wiring and reset headlamp focusing	\$ 17 80.00 X
2	To provide labour	\$ 420.00 300
3	To repair body frame	\$ 17 480.00 X
		\$ 980.00
Grand Total		\$ 7,061.70

Singapore Dollars: Seven Thousand Sixty-One and Cents: Seventy only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

P-2483
102
223470
506
300
30407
202
2432