

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

AIG

Owner : Lee Chee Meng (82282180)

Accident Date : 20-Aug-24

Vehicle No : FBP4247X(COE : 300519-290529)

Vehicle Model : Yamaha Sniper T150

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Front fork tube assy	\$ 640.00
1	Fork under bracket	\$ 220.00
1	Front wheel rim	\$ 485.00
1	Front rim shaft	\$ 105.00
1	Front rim bearing	\$ 88.00
1	Front brake disc	\$ 185.00
1	Handle-bar	\$ 280.00
1	Handle-bar end	\$ 120.00
1	Hand grip (1 set)	\$ 98.00
1	Head Lamp	\$ 485.00
1	Head Lamp Cover	\$ 135.00
1	Side mirror - 1 set	\$ 128.00
1	Clutch lever	\$ 105.00
1	Front signal - 1 set	\$ 160.00
1	Pilot light	\$ 380.00
1	Horn inner panel	\$ 150.00
1	Front inner cover	\$ 190.00
1	Fairing assy (1 set)	\$ 680.00
1	Front footrest bracket	\$ 216.00
2	Front footrest	\$ 158.00
1	Gear pedal	\$ 135.00
2	Rear footrest	\$ 150.00
2	Reat footrest bracket	\$ 360.00
		\$ 5,653.00
Less 10%		\$ 565.30
		\$ 5,087.70

Special Net Items

1	Number plate (1 set)	\$ 38.00
2	Fork oils	\$ 30.00
2	Fork oil seals	\$ 56.00
1	Steering cone (1 set)	\$ 90.00
1	Sticker (1 set)	\$ 120.00
1	Rear box	\$ 480.00
1	Rear box bracket	\$ 180.00
		\$ 994.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Lee Chee Meng (82282180)

Accident Date : 20-Aug-24


Vehicle No : **FBP4247X(COE : 300519-290529)**

Vehicle Model : Yamaha Sniper T150

Estimated Repair Costs

S/No.	Labour	
1	To ckeck wiring and reset headlamp focusing	\$ 17 80.00 X
2	To provide labour	\$ 420.00 200
3	To repair body frame	\$ 17 480.00 X
		\$ 980.00
Grand Total		\$ 7,061.70

Singapore Dollars: Seven Thousand Sixty-One and Cents: Seventy only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

P-1653
102
1487.70
446
200
2133.70
202
1706.