

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

MS FIRST CAPITAL INSURANCE LIMITED

6 Raffles Quay
#21-00
Singapore 048580

Tel: 62222311

Fax: 62223547

Attn: Motor Claim Department

Your Ref No: TP 0824-8218

Claim Type: Third Party

Accident Date: 29 August 2024

TP Veh Reg No: SHA3993P

Estimate No: EST1511726

Date: 30 Aug 2024

Policy No: DMCPhQ24-001015

Veh Reg No: GBJ5658T

Make/Model: TOYOTA HIACE DX 2.8
AUTO

Chassis No: GDH2012005207

Engine No: 1GD8389493

Reg. Date: 31 May 2019

Estimate Repair Cost to Vehicle No: GBJ5658T

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 FRONT BUMPER	836.70	1 PC	836.70	✓
2 FRONT BUMPER SIDE RETAINER - LH/RH	217.70	2 PC	435.40	X
3 FRONT BUMPER CLIPS	5.50	10 PC	55.00	✓
4 FRONT BUMPER CENTER LOWER GRILLE	248.60	1 PC	248.60	✓
5 FRONT BUMPER FOGLAMP COVER - LH/RH	96.90	2 PC	193.80	X
6 FRONT BUMPER TOW COVER - LH/RH	40.80	2 PC	81.60	X
7 FRONT BUMPER REINFORCEMENT (LOWER)	551.50	1 PC	551.50	X
8 FRONT BUMPER REINFORCEMENT (LOWER BRACKET - LH/RH	75.50	2 PC	151.00	X
9 FRONT BUMPER REINFORCEMENT (TOP)	211.70	1 PC	211.70	X
10 FRONT BUMPER REINFORCEMENT (TOP) BRACKET - LH/RH	233.10	2 PC	466.20	X
11 BRACE PANEL	60.20	1 PC	60.20	X
12 BONNET LOGO	70.80	1 PC	70.80	X
13 GRILLE BASE	483.40	1 PC	483.40	X
14 GRILLE OUTER TOP GARNISH	193.70	1 PC	193.70	X
15 GRILLE OUTER LOWER GARNISH	535.60	1 PC	535.60	X
16 GRILLE RADAR COVER	1,527.80	1 PC	1,527.80	X
17 FRONT GRILLE CLIPS	5.50	8 PC	44.00	X
18 RADAR SENSOR	1,953.60	1 PC	1,953.60	X
19 HEADLAMP - LH/RH	4,033.10	2 PC	8,066.20	X
20 REAR BUMPER	661.90	1 PC	661.90	✓
21 REAR BUMPER SIDE RETAINER (UPPER) - LH/RH	35.80	2 PC	71.60	✓
22 REAR BUMPER SIDE RETAINER (LOWER) - LH/RH	35.80	2 PC	71.60	✓
23 REAR BUMPER CLIPS	5.50	10 PC	55.00	✓
24 REAR BUMPER BRACKET - LH/RH	36.20	4 PC	144.80	✓
25 REAR BUMPER CORNER PANEL - LH/RH	142.10	2 PC	284.20	✓
26 TAILGATE	3,106.80	1 PC	3,106.80	✓
27 TAILGATE HINGE - LH/RH	104.00	2 PC	208.00	✓
28 TAILGATE TOP LOCK	383.60	1 PC	383.60	✓
29 TAILGATE LOWER LOCK	105.60	1 PC	105.60	✓
30 TAILGATE TOYOTA LOGO	78.70	1 PC	78.70	✓
31 TAILGATE OUTER GARNISH, BLACK	197.10	1 PC	197.10	✓
32 TAILGATE WEATHERSTRIP	565.40	1 PC	565.40	✓
33 TAILGATE "HIACE" STICKER	60.60	1 PC	60.60	✓
34 TAILLAMP - LH/RH	471.70	2 PC	943.40	✓
35 TAILLAMP PANEL (OUTER) - LH	787.00	1 PC	787.00	✓
36 TAILLAMP PANEL (INNER) - LH	400.00	1 PC	400.00	✓
37 REAR END PANEL (OUTER)	395.00	1 PC	395.00	✓
38 REAR END PANEL (INNER)	1,283.40	1 PC	1,283.40	✓
39 REAR END PANEL TOP GARNISH	146.80	1 PC	146.80	✓
40 REAR FLOOR PANEL	3,315.40	1 PC	3,315.40	✓
41 REAR EXHAUST	850.80	1 PC	850.80	✓

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@proccarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

	30,283.50	
Less 25%	-7,570.20	22,713.30

Special Net

42	FRONT NUMBER PLATE	35.00	1 PC	SUR	35.00	✓
43	REAR NUMBER PLATE	35.00	1 PC	17	35.00	X
44	8 PAX STICKER	15.00	1 PC	121	15.00	10
45	70 KM/H STICKER	15.00	1 PC	121	15.00	10
46	SEALANT	20.00	2 PC	121	40.00	11
47	SPONGE TAPE	20.00	1 PC	121	20.00	11
48	REAR BUMPER SENSOR	200.00	1 PC	121	200.00	200
49	WOODEN BOARD	1,000.00	1 PC	17	1,000.00	X
50	REAR GOGO STICKER	300.00	1 PC	121	300.00	X
						1,660.00

Labour

51	FRONT - TO KNOCK DENTS, REMOVE, REPLACE ACCIDENT PORTIONS-	600.00	1 JOB		600.00	300
52	REAR - TO KNOCK OUT DENTS ON REAR BOTH CHASSIS, CUT/WELD END PANEL (INNER & OUTER), FLOOR PANEL, REMOVE, REPLACE ACCIDENT PORTIONS -	1,400.00	1 JOB		1,400.00	✓
53	TO RESPRAY PAINT ON ACCIDENT PORTION-	1,200.00	1 JOB		1,200.00	1100
54	TO CHECK WIRING, FRT AND REAR -	60.00	1 JOB		60.00	30
55	TO REMOVE, REPLACE REAR BUMPER SENSOR	80.00	1 JOB		80.00	30
56	TO TUFF-KOTE-	120.00	1 JOB		120.00	80
57	TO REMOVE, REPLACE REAR GLASS-	150.00	1 JOB		150.00	100
58	TO REMOVE, REPLACE REAR EXHAUST PIPE -	100.00	1 JOB	11	100.00	X
59	TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR-	150.00	1 JOB	11	150.00	X
60	TO TRANSFER TAILGATE FITTINGS-	100.00	1 JOB		100.00	60
						3,960.00

~~refill air con gas \$100~~

~~condenser run \$2099.80~~

~~30.00 extra cover back 91.00 Tom~~

Total	28,333.30
Add GST @ 9%	2,550.00
Total Amount Payable SGD	30,883.30

SINGAPORE DOLLAR THIRTY THOUSAND EIGHT HUNDRED EIGHTY THREE AND CENTS THIRTY ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

MS FIRST CAPITAL INSURANCE LIMITED

6 Raffles Quay

#21-00

Singapore 048580

Tel: 62222311

Fax: 62223547

Attn: Motor Claim Department

Your Ref No: TP 0824-8218

Claim Type: Third Party

Accident Date: 29 August 2024

TP Veh Reg No: SHA3993P

Estimate No: EST1511726

Date: 24 Sep 2024

Policy No: DMCPHQ24-001015

Veh Reg No: GBJ5658T

Make/Model: TOYOTA HIACE DX 2.8
AUTO

Chassis No: GDH2012005207

Engine No: 1GD8389493

Reg. Date: 31 May 2019

Estimate Repair Cost to Vehicle No: GBJ5658T

Description	Unit Price	Quantity	List Price SGD	Amount SGD
Supplementary Parts to Repair				
List Price				
1 AIRCON CONDENSER-	2,099.80	1 PC	2,099.80	
2 TAILGATE TOP COVER-	91.00	1 PC	91.00	
			2,190.80	
		Less 25%	-547.60	1,643.20
Labour				
3 TO REFILL GAS-	100.00	1 JOB	100.00	100.00

Total 1,743.20

Add GST @ 9% 156.89

Total Amount Payable SGD 1,900.09

SINGAPORE DOLLAR ONE THOUSAND NINE HUNDRED AND CENTS NINE ONLY

SUP 1743.20
PARTS 13695.37
JN 615.00
LAB 2900.00
18953.57
1/3 = 15150

P-20245.9
15041.93
315
3200
18556.93
202
14845

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE