

CHK auto.

ESTIMATE TO REPAIR

VEHICLE NO. : SNR 6803 A
MAKE : HYUNDAI
MODEL : SX2 KONA 1.6 GDI HEV
YEAR : 2024
CHASSIS NO : KMHHB811VRU071106

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 04.09.2024
DATE OF ACCIDENT : 23.08.2024
THIRD PARTY REF : SHB 5597 G
THIRD PARTY REF : MS FIRST CAPITAL INSURANCE LTD
6 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
Singapore 048581

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front bumper				\$ 720.00
1 pc	Front bumper lower				\$ 1,100.00
1 pc	Front bumper sensor				\$ 225.00
1 pc	Right head lamp				\$ 2,216.00
	less .20%				\$ 4,267.00
			2316.00		\$ 853.40
			663.00		\$ 3413.60
	To putty and spray paint		2652.00		\$ 300.00
	To check front wiring & focus headlight		420.00		\$ 30.00
	Labour charges		3072.00		\$ 380.00
TG/BN	TOTAL	PBP			\$ 5,830.40

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64509127 Email: admin@lmtm.sg
Co. Reg No. 199307277D GST Reg No. M2-0019066-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd

Not Wholesaler
Repair By paint
2 days
@ 3072.80