

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **PC5278C**
 MODEL : **TOYOTA HIACE COMMUTER**
 DATE OF ACCIDENT : 01.09.2024
 TIME OF ACCIDENT : 16:25 HOURS

22	REAR SPARE TYRE HOLDER BOLT <i>Not m</i>	1	\$ 60.00	\$ 60.00
----	--	---	----------	----------

6810
 5107.50

TOTAL PRICE	\$ 12,438.00
LESS 25%	\$ 3,109.50
SUB TOTAL PRICE	\$ 9,328.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Ne m</i>	1	\$ 50.00	\$ 50.00
2	REAR NUMBER PLATE (THAI WORD)STICKER <i>Ne m</i>	1	\$ 150.00	\$ 150.00
3	REAR BUMPER (SPECAIL TYPE) <i>Distaled</i>	1	\$ 2,500.00	\$ 2,500.00
4	REAR BUMPER STICKER (CARBON FIBER) <i>Ne m</i>	1	\$ 200.00	\$ 200.00
5	REAR BUMPER CLIP (SET) <i>Ne m</i>	1	\$ 80.00	\$ 80.00
6	TAILGATE SEALANT <i>Ne m</i>	1	\$ 150.00	\$ 150.00
7	TAILGATE CENTER MOULDING CLIP (SET) <i>Ne m</i>	1	\$ 30.00	\$ 30.00
8	TAILGATE CENTER MOULDING STICKER(CHROME) <i>Ne m</i>	1	\$ 120.00	\$ 120.00
9	TAILGATE STICKER 'EMERGENCY DOOR' <i>Ne m</i>	1	\$ 40.00	\$ 40.00
10	TAILGATE STICKER '70KM/H' <i>Not m</i>	1	\$ 30.00	\$ 30.00
11	TAILGATE INNER LEATHER (SPECAIL TYPE) <i>Ne m</i>	1	\$ 1,200.00	\$ 1,200.00
12	TAILGATE WINDSCREEN SEALANT <i>Ne m</i>	1	\$ 80.00	\$ 80.00
13	TAILGATE WINDSCREEN INNER SEAL <i>Ne m</i>	1	\$ 60.00	\$ 60.00
14	TAILGATE AUTO SYSTEM (SPECAIL TYPE)(SET) <i>Ne m</i>	1	\$ 2,200.00	\$ 2,200.00
15	TAIL LAMP CLIP (SET) <i>Ne m</i>	1	\$ 50.00	\$ 50.00
16	TAILLAMP LOWER GARNISH CLIP (SET) <i>Ne m</i>	1	\$ 40.00	\$ 40.00
17	REAR END PANEL (INNER) SEALANT <i>Ne m</i>	1	\$ 150.00	\$ 150.00
18	REAR END PANEL (OUTER) SEALANT <i>Ne m</i>	1	\$ 150.00	\$ 150.00
19	REAR FLOOR PANEL SEALANT <i>Ne m</i>	1	\$ 250.00	\$ 250.00
20	REAR FLOOR PANEL SOUND PROOF (SPECIAL TYPE) <i>Ne m</i>	1	\$ 1,800.00	\$ 1,800.00
21	REAR FLOOR PANEL CHROME (SPECIAL TYPE) <i>Set</i>	1	\$ 800.00	\$ 800.00
22	REAR FLOOR PANEL TOP BOARD (SPECIAL TYPE) <i>Ne m</i>	1	\$ 2,500.00	\$ 2,500.00
23	REVERSE SENSOR <i>Ne m</i>	1	\$ 220.00	\$ 220.00

2810 TOTAL \$ 12,850.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
-----	-----------------	-------	---------------

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **PC5278C**
 MODEL : **TOYOTA HIACE COMMUTER**
 DATE OF ACCIDENT : 01.09.2024
 TIME OF ACCIDENT : 16:25 HOURS

1	PANEL BEATING AND REPLACE PARTS	\$ 2,600.00	800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,200.00	800
3	WIRNING, BULB CHECKING	\$ 80.00	30
4	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
5	TRANSFER TAILGATE MECHAISM	\$ 80.00	60
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	+
7	REAR CHASSIS ALIGHMENT	\$ 250.00	+
8	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓
9	REMOVE AND REFIX REAR FLOOR BOARD MAT	\$ 200.00	+
10	REMOVE AND REFIX REAR TAILGATE SPOILER	\$ 150.00	+
11	REMOVE AND REFIX TAILGATE ACCESSORIES AND CURTAIN	\$ 450.00	300
12	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	50
13	REMOVE AND REFIX VIDEO CAMERA	\$ 80.00	50

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **PC5278C**
 MODEL : **TOYOTA HIACE COMMUTER**
 DATE OF ACCIDENT : **01.09.2024**
 TIME OF ACCIDENT : **16:25 HOURS**

14	REMOVE AND REFIX REVERSE CAMERA	\$ 80.00	50
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

2380

TOTAL \$6,790.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 22,178.50
 TOTAL LABOUR COST : \$ 6,790.00
 TOTAL REPAIR COST : \$ 28,968.50

Adm
 L/S 04/09/24
 07. Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

total: 90297.50
 L/S: 8.2/K

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

8.2/K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: