

Not Notified  
L1 Rm @ 1150/h

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

**SHC5112S**

**AAD2401-122**

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

**03 SEP 2024**

SHC5112S

JTDKB3FU703092107

200303878K

TOYOTA

PRIUS GEN 4

27/1/2024

SHC3720A/FCI

30/9/2020

PART
1 COVER, REAR BUMPER
1 COVER, REAR BUMPER, LOWER
1 GUARD, REAR BUMPER, CENTER
1 SEAL, REAR BUMPER SIDE, LH
1 SEAL, REAR BUMPER SIDE, RH
1 RETAINER, REAR BUMPER SIDE, LH
1 REAR BUMPER SIDE RETAINER RH
1 REINFORCEMENT SUB-ASSY, REAR BUMPER
1 REFLECTOR ASSY, REFLEX, LH
1 LENS & BODY, REAR COMBINATION LAMP, LH
1 LENS & BODY, REAR COMBINATION LAMP, NO.2 LH
1 COVER, REAR COMBINATION LAMP, LH
1 COVER, FLOOR UNDER, RH
1 COVER, FLOOR UNDER, LH
1 COVER, REAR FLOOR
1 PANEL SUB-ASSY, QUARTER, LH
1 LINER, REAR WHEEL HOUSE, LH
1 COVER, DECK TRIM, REAR
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
1 PLATE, BACK DOOR NAME, NO.1
1 ORNAMENT SUB-ASSY, BACK DOOR

LIST
\$ B 612.68 ✓
\$ L 27.93 X
\$ BTR 472.19 ✓
\$ L 149.21 X
\$ L 149.21 X
\$ L 167.48 X
\$ L 167.48 X
\$ R 419.90 X
\$ L 49.25 ✓
\$ L 428.19
\$ L 329.49
\$ L 88.41
\$ L 220.50
\$ L 304.92
\$ L 290.43
\$ R 1,099.46
\$ L 176.09
\$ L 159.39
\$ L 1,156.89
\$ ~ 68.88
\$ ~ 68.88
\$ ~ 90.30
<b>TOTAL \$ 6,697.16</b>
25% \$ <b>1,674.29</b>
<b>\$ 5,022.87</b>

**SPECIAL NETT**

1SET PARKING AID

1 REAR BUMPER CLIP

\$ L 700.00 X  
\$ L 65.00 60.00

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

**SHC5112S**

- 1 REAR RH BUMPER RETAINER CLIP
- 1 FENDER LINER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR

**AAD2401-122**

\$	nn	65.00	X
\$	nn	65.00	X
\$	nn	60.00	X
\$	nn	180.00	305ne
TOTAL		\$	1,135.00
TOTAL PARTS		\$	6,157.87

**LABOUR**

To rust-proofing of the affected areas.	\$	nn	600.00	X
Putty and spray painting of the affected portion.	\$		1,200.00	2201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	2001
To transfer of tailgate fittings and conduct water seepage test.	\$	nn	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4	380.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	4	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	4	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	501
To check steering geometry and computer wheel alignment	\$	4	220.00	X
TOTAL		\$	5,080.00	

**OVERALL TOTAL \$ 11,237.87***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: