

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SMADMIN@SM-AUTOMOTIVE.SG

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

02/09/2024

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date : 01/09/2024

Estimated repair cost for vehicle no : SMF8631R MITSUBISHI OUTLANDER 2.0 CVT

CHASSIS: GF7W0600240 (2018)

| S/N | Qty | Items                                                | U/price    | Amount     |
|-----|-----|------------------------------------------------------|------------|------------|
| 1   | 1   | FRONT BUMPER <i>863</i>                              | \$1,148.00 | \$1,148.00 |
| 2   | 1   | LH FRONT BUMPER LOWER SIDE PROTECTOR <i>cut</i>      | \$87.00    | \$87.00    |
| 3   | 1   | LH FRONT BUMPER TOP CHROME <i>new</i>                | \$338.00   | \$338.00   |
| 4   | 1   | FRONT BUMPER SIDE RETAINER <i>new</i>                | \$23.00    | \$23.00    |
| 5   | 1   | FRONT BUMPER UNDER COVER <i>new</i>                  | \$198.00   | \$198.00   |
| 6   | 1   | LH FRONT FENDER <i>Dented</i>                        | \$652.00   | \$652.00   |
| 7   | 1   | LH FRONT FENDER INNER COWLING <i>Dented</i>          | \$185.00   | \$185.00   |
| 8   | 1   | LH FRONT FENDER OUTER PROTECTOR <i>cut</i>           | \$178.00   | \$178.00   |
| 9   | 1   | LH FRONT HEADLAMP <i>cracked</i>                     | \$2,295.00 | \$2,295.00 |
| 10  | 1   | LH FRONT HEADLAMP LOWER BRACKET <i>new</i>           | \$38.00    | \$38.00    |
| 11  | 1   | LH FRONT LOWER ARM <i>cut</i>                        | \$385.00   | \$385.00   |
| 12  | 1   | LH FRONT KNUCKLER ARM <i>new</i>                     | \$339.00   | \$339.00   |
| 13  | 1   | LH FRONT KUNCKLER ARM WHEEL BEARING <i>new</i>       | \$352.00   | \$352.00   |
| 14  | 1   | LH FRONT SHOCK ABSORBER <i>new</i>                   | \$368.00   | \$368.00   |
| 15  | 1   | LH FRONT DOOR <i>Dented</i>                          | \$981.00   | \$981.00   |
| 16  | 2   | LH FRONT DOOR HINGE <i>new</i>                       | \$68.00    | \$68.00    |
| 17  | 1   | LH FRONT DOOR CHECKER <i>new</i>                     | \$74.00    | \$74.00    |
| 18  | 1   | LH FRONT DOOR PROTECTOR <i>missing</i>               | \$189.00   | \$189.00   |
| 19  | 1   | LH FRONT DOOR INNER TRIM BOARD <i>behind</i>         | \$568.00   | \$568.00   |
| 20  | 1   | LH FRONT DOOR LOCK <i>new</i>                        | \$378.00   | \$378.00   |
| 21  | 1   | LH FRONT DOOR POWER WINDOW REGULATOR GEAR <i>new</i> | \$210.00   | \$210.00   |
| 22  | 1   | LH FRONT DOOR POWER WINDOW MOTOR <i>new</i>          | \$550.00   | \$550.00   |
| 23  | 1   | LH FRONT DOOR WEATHER STRIPE <i>new</i>              | \$194.00   | \$194.00   |
| 24  | 1   | LH FRONT DOOR BLACK STICKER <i>new</i>               | \$85.00    | \$85.00    |
| 25  | 1   | LH SIDE ROCKER PANEL <i>Dented</i>                   | \$981.00   | \$981.00   |
| 26  | 1   | LH SIDE ROCKER PANEL OUTER GARNISH <i>behind</i>     | \$688.00   | \$688.00   |
| 27  | 1   | LH REAR DOOR <i>Dented</i>                           | \$981.00   | \$981.00   |
| 28  | 2   | LH REAR DOOR HINGE <i>new</i>                        | \$68.00    | \$68.00    |
| 29  | 1   | LH REAR DOOR CHECKER <i>new</i>                      | \$74.00    | \$74.00    |
| 30  | 1   | LH REAR DOOR PROTECTOR <i>missing</i>                | \$189.00   | \$189.00   |
| 31  | 1   | LH REAR DOOR INNER TRIM BOARD <i>new</i>             | \$568.00   | \$568.00   |
| 32  | 1   | LH REAR DOOR LOCK <i>new</i>                         | \$378.00   | \$378.00   |

TP 1st Cap.  
Hui Roy



SMF8631R MITSUBISHI OUTLANDER

|    |   |                                          |       |            |            |   |
|----|---|------------------------------------------|-------|------------|------------|---|
| 33 | 1 | LH REAR DOOR POWER WINDOW REGULATOR GEAR | And   | \$210.00   | \$210.00   | ✓ |
| 34 | 1 | LH REAR DOOR POWER WINDOW MOTOR          | new   | \$550.00   | \$550.00   | ✓ |
| 35 | 1 | LH REAR DOOR WEATHER STRIPE              | new   | \$194.00   | \$194.00   | + |
| 36 | 1 | LH REAR DOOR BLACK STICKER               | new   | \$85.00    | \$85.00    | ✓ |
| 37 | 1 | LH REAR FENDER                           | Paint | \$1,315.00 | \$1,315.00 | + |
| 38 | 1 | LH REAR FENDER OUTER PROTECTOR           | new   | \$188.00   | \$188.00   | ✓ |
| 39 | 1 | LH REAR FENDER INNER COWLING             | new   | \$185.00   | \$185.00   | + |
| 40 | 1 | LH REAR SHOCK ABSORBER                   | new   | \$291.00   | \$291.00   | + |
| 41 | 1 | LH REAR LOWER ARM                        | Best  | \$196.00   | \$196.00   | ✓ |
| 42 | 1 | LH REAR KNUCKLER ARM                     | Best  | \$396.00   | \$396.00   | ✓ |
| 43 | 1 | LH REAR TRAILING ARM                     | Best  | \$596.00   | \$596.00   | ✓ |
| 44 | 1 | LH REAR KNUCKLER ARM WHEEL BEARING       | new   | \$520.00   | \$520.00   | ✓ |

TOTAL : \$18,536.00

LESS 10 % \$1,853.60

SUB-TOTAL : \$16,682.40

| S/N | Qty | ITEMS / SPECIAL NETT                 | U/price    | Amount     |
|-----|-----|--------------------------------------|------------|------------|
| 1   | 1   | FRONT BUMPER CLIPS                   | \$80.00    | \$80.00    |
| 2   | 1   | LH FORNT RIM                         | \$1,100.00 | \$1,100.00 |
| 3   | 1   | LH FRONT TYRE                        | \$550.00   | \$550.00   |
| 4   | 1   | LH REAR RIM                          | \$1,100.00 | \$1,100.00 |
| 5   | 1   | LH REAR TYRE                         | \$550.00   | \$550.00   |
| 6   | 1   | LH ROCKER PANEL OUTER GARNISH CLIPS  | \$80.00    | \$80.00    |
| 7   | 1   | LH REAR FENDER QUARTER GLASS SEALANT | \$120.00   | \$120.00   |
| 8   | 1   | LH FRONT DOOR INNER TRIM BOARD CLIPS | \$60.00    | \$60.00    |
| 9   | 1   | LH REAR DOOR INNER TRIM BOARD CLIPS  | \$60.00    | \$60.00    |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

- Modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Labour charges

|   |                                                              |      |            |
|---|--------------------------------------------------------------|------|------------|
| 1 | LABOUR FOR PANEL BEATING                                     | 1400 | \$2,000.00 |
| 2 | LABOUR FOR SPRAYPAINTING                                     | 1100 | \$1,800.00 |
| 3 | WIRING CHECK                                                 | 30   | \$80.00    |
| 4 | LABOUR FOR REMOVE & TRANSFER BOTH LH FRONT/REAR DOOR FITTING | 160  | \$500.00   |
| 5 | LABOUR FOR REMOVE & REFIX LH REAR FENDER QUARTER GLASS       | 2830 | \$150.00   |
| 6 | LABOUR FOR REMOVE & RENEW FRONT UNDER CARRIAGE               | 200  | \$300.00   |
| 7 | LABOUR FOR REMOVE & RENEW REAR UNDER CARRIAGE                | 80   | \$150.00   |
| 8 | TO CONDUCT WHEEL ALIGNMENT                                   |      |            |

Subtotal :- \$5,280.00

Total:- \$25,662.40

13.3K

2/S. 04/09/24. 10 Days.

total: 16614.90 4/S: 13.3K