

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP Chinn.
Veron.

MOHAMAD HAZIQ BIN MOHAMAD NASIR
JURI
812 YISHUN RING RD #04-4157
SINGAPORE 760812

TAX INVOICE

Repair Code : CLM18266

Date in : 10/06/2024

Vehicle Num. : SJG8368G

Model : B.M.W. 320I A

Chassis/Eng# : WBAWK72040P231398/N43B20AAA4671489

Contact : 97663577

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dehid</i>	1	1876.50	1,876.50 1480
REAR BUMPER PARKING SENSOR 'O' RING	4	22.00	+ 88.00
REAR BUMPER PARKING SENSOR HOLDER	4	25.00	+ 100.00
REAR BUMPER RH PARKING SENSOR	1	617.50	+ 617.50
REAR BUMPER SIDE RETAINER RH <i>Cuked</i>	1	235.00	235.00 160
REAR BUMPER UNDER COVER <i>Are m</i>	1	406.00	+ 406.00
REAR RH CONTROL ARM (BOTTOM) <i>Bent</i>	1	697.79	- 697.79
REAR RH CONTROL ARM (TOP) <i>Bent</i>	1	496.50	- 496.50
REAR RH FENDER <i>Distorted</i>	1	2107.40	✓ 2,107.40
REAR RH FENDER INNER SHIELD COVER <i>torn</i>	1	354.60	354.60 225
REAR RH FENDER INNER TRIM GARNISH <i>Are m</i>	1	495.20	+ 495.20
REAR RH KNUCKLE ARM	1	1765.00	1,765.00 1310
REAR RH KNUCKLE ARM BEARING <i>Damaged</i>	1	510.50	✓ 510.50
REAR RH LOWER ARM <i>Bent</i>	1	635.20	✓ 635.20
REAR RH SHOCK ABSORBER <i>Bent</i>	1	877.67	877.67 680
REAR RH TAILLAMP <i>Are m</i>	1	812.00	+ 812.00
REAR RH TRAILING ARM <i>Bent</i>	1	435.67	✓ 435.67
REAR RH UPPER ARM <i>Bent</i>	1	500.70	✓ 500.70

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MOHAMAD HAZIQ BIN MOHAMAD NASIR
JURI
812 YISHUN RING RD #04-4157
SINGAPORE 760812

Contact : 97663577

TAX INVOICE

Repair Code : CLM18266
Date in : 10/06/2024
Vehicle Num. : SJG8368G
Model : B.M.W. 320I A
Chassis/Eng# : WBAWK72040P231398/N43B20AAA467I489

		Subtotal before discount	13,011.23
Percentage discount	5%	9238.76	650.56
		8776.82	
		Sub-total 1	12,360.67
REAR BUMPER CLIPS - SET	new	1	50.00 ✓ 50.00
REAR RH FENDER INNER SHIELD COVER CLIPS - SET	new	1	30.00 ✓ 30.00
REAR RH FENDER INNER TRIM GARNISH CLIPS - SET	new new	1	50.00 x 50.00
REAR RH SPORT RIM	new new	1	1200.00 x 1,200.00
REAR RH TYRE	new new	1	480.00 x 480.00
		Subtotal before discount	1,810.00
Percentage discount	0%		0.00
		Sub-total 2	1,810.00
		Parts-total	14,170.67

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	50	80.00 ✓
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knucke arm, wheel bearing, bearing hub and etc.	250	380.00 ✓
To road test driving, check and resetting wheel alignments system.	80	100.00 ✓
To remove, reinstall petrol tank. (to FR)	60	100.00 ✓
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60	240.00 ✓
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	400	800.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MOHAMAD HAZIQ BIN MOHAMAD NASIR
JURI
812 YISHUN RING RD #04-4157
SINGAPORE 760812

Contact : 97663577

TAX INVOICE

Repair Code : CLM18266

Date in : 10/06/2024

Vehicle Num. : SJG8368G

Model : B.M.W. 320I A

Chassis/Eng# : WBAWK72040P231398/N43B20AAA4671489

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

1560 6w 1,600.00
60 100.00

Labour Total

3,400.00

Parts & Labour Total

17,570.67

*** This is a computer-generated document which requires no signature.***

page 3

total: 10416.82
L/S: 8.3K ✓
06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: