

Not Authorized
61 Smp @ 3350/h

Trans-cab Auto Services Pte Ltd

AAD2406-073

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5135B

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

19 JUN 2024

SHC5135B

JTDKB3FU203092239

200303878K

TOYOTA

PRIUS GEN 4

15/6/2024

SMJ4084A/ II

16/10/2020

PART

- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 MOULDING, FRONT BUMPER SIDE, RH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 EMBLEM, SIDE PANEL, RH
- 1 UNIT ASSY, HEADLAMP, RH
- 1 MIRROR ASSY, OUTER REAR VIEW, RH

LIST

\$	Bulw	653.31	✓
\$	Sn	100.91	X
\$	n	902.16	X
\$	Sn	100.49	X
\$	Sn	120.86	X
\$	Sn	532.88	X
\$	Sn	224.70	X
\$	Sn	276.15	X
\$	Bu	1,236.69	✓
\$	DIY	255.36	✓
\$	me	68.88	✓
\$	Sn	3,325.56	X
\$	nd \$ Tu	1,814.09	✓
TOTAL	\$	9,612.04	
25%	\$	2,403.01	
	\$	7,209.03	

Special Nett

- 1 FRT BUMPER CLIP
- 1 FENDER LINER CLIP
- 1 FRT BUMPER SIDE RETAINER CLIP

\$	me	65.00	60sn
\$	me	65.00	60sn
\$	na	65.00	X
TOTAL	\$	195.00	

TOTAL PARTS \$ 7,404.03

LABOUR

Trans-cab Auto Services Pte Ltd**AAD2406-073**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5135B

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	5001
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	4501
To check steering geometry and computer wheel alignment	\$	220.00	801
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	4,990.00	
Over All Total	\$	12,394.03	

(PART-BY-PART) Repair Days**07 Days****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: