

ASS. REC. BY:

REF:

TH / 240624 / Kuna3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 5135B

Yr Regn:

10, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Provs

c.c.

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

354273

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKBB3FU203092239

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wanli

Front

Rear

R/Bal.

9

mm

R/Bal.

3

mm

L/Bal.

9

mm

L/Bal.

3

mm

D.O.A.

15/6/24

D.O.I.

19/6/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 15m

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Got BZ, got video footage.

2016 11 Pm @ 3350h. Cnhr

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fixes

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Not Authorized
L1 Smp & 3350/h

Trans-cab Auto Services Pte Ltd

AAD2406-073

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5135B

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

19 JUN 2024

SHC5135B

JTDKB3FU203092239

200303878K

TOYOTA

PRIUS GEN 4

15/6/2024

SMJ4084A/IL

16/10/2020

PART	
1	COVER, FRONT BUMPER
1	ABSORBER, FRONT BUMPER ENERGY
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER
1	SUPPORT, FRONT BUMPER SIDE, RH
1	MOULDING, FRONT BUMPER SIDE, RH
1	GRILLE SUB-ASSY, RADIATOR
1	GRILLE, RADIATOR, LOWER NO.1
1	JAR ASSY, WINDSHIELD WASHER
1	FENDER SUB-ASSY, FRONT RH
1	LINER, FRONT FENDER, RH
1	EMBLEM, SIDE PANEL, RH
1	UNIT ASSY, HEADLAMP, RH
1	MIRROR ASSY, OUTER REAR VIEW, RH

LIST	
\$	Bulw 653.31 ✓
\$	Sh 100.91 X
\$	n 902.16 X
\$	Sh 100.49 X
\$	Sh 120.86 X
\$	Sh 532.88 X
\$	Sh 224.70 X
\$	Sh 276.15 X
\$	Buc 1,236.69 ✓
\$	Diy 255.36 ✓
\$	Mc 68.88 ✓
\$	Sh 3,325.56 X
\$	Det \$/Tn 1,814.09 ✓
TOTAL	\$ 9,612.04
25%	\$ 2,403.01
	\$ 7,209.03

Special Nett

1	FRT BUMPER CLIP
1	FENDER LINER CLIP
1	FRT BUMPER SIDE RETAINER CLIP

\$	Mc 65.00 6052
\$	Mc 65.00 6052
\$	nn 65.00 X
TOTAL	\$ 195.00

TOTAL PARTS \$ 7,404.03

LABOUR

Trans-cab Auto Services Pte Ltd**AAD2406-073**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5135B

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	5001
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	4501
To check steering geometry and computer wheel alignment	\$	220.00	801
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	4,990.00	
Over All Total	\$	12,394.03	

(PART-BY-PART) Repair Days**07 Days****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 878K

Vehicle Details

Vehicle No.: SHC5135B

Vehicle to be Exported: Yes

Intended Deregistration Date: 18 Jun 2024

Vehicle Make: TOYOTA

Vehicle Model: PRIUS 5DR HATCHBACK (AUTO)

Primary Colour: Red

Manufacturing Year: 2020

Engine No.: 2ZR2H02481

Chassis No.: JTDKB3FU203092239

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$26,807.00

Original Registration Date: 16 Oct 2020

First Registration Date: 16 Oct 2020

Transfer Count: 0

Actual ARF Paid: \$14,530.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 15 Oct 2028

PARF Rebate Amount: \$10,897.00

Intended COE Rebate Details

COE Expiry Date: 15 Oct 2028

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$28,160.00

COE Rebate Amount: \$15,219.00

Total Rebate Amount: \$26,116.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Jun 2024

OK