

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMR24090040/Uvp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNP23707at Workshop m/s M

of _____

Insured: SMB11837

Policy No. _____

Claims No. TAX/08/24/2105


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$58k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 628d

Vehicle: IN / OUT

214918980Veh No: SNP23707Yr Regn: 25/06/18Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Mondeoc.c 1496Colour: Red

A/C: Insured / Std / NI / NA

Sp.Reading: 145752

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK81202179Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/50 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or henhookFront 6Rear 6R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 31/8/24D.O.I. 03/9/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/9/24 L/S & 6700 in hand 4101 (red 14,403.60, 68%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$) _____

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	628D

Vehicle Details

Vehicle No.:	SNP2370T
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Sep 2024
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	L15B5462536
Chassis No.:	GK81202179
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$19,202.00
Original Registration Date:	25 Jun 2018
First Registration Date:	25 Jun 2018
Transfer Count:	1
Actual ARF Paid:	\$9,202.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jun 2028
PARF Rebate Amount:	\$5,981.00

Intended COE Rebate Details

COE Expiry Date:	24 Jun 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,110.00
COE Rebate Amount:	\$12,999.00
Total Rebate Amount:	\$18,980.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 02 Sep 2024

OK

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Authorized
for
works

3/9/24

5 days 4/5 # 6700
Alph. Atamp-

VEHICLE No: SNP 2370T

1PC	REAR WINDSCREEN MOULDING	new		\$166.20	✓
1PC	TAILGATE	Body 2D	1193.00	\$1,455.20	✓
1PC	TAILGATE REAR LOGO	one		\$48.00	✓
2PCS	TAILGATE REFLECTORS @\$341.60	svc		\$683.20	X
1PC	TAILGATE OUTER GARNISH	one	381.20	\$495.00	✓
1PC	TAILGATE INNER LOCK	surf	245.50	\$288.20	✓
1PC	TAILGATE INNER TRIM BOARD	de / torn		\$455.10	✓
1PC	TAILGATE WEATHERSTRIP	twi		\$232.80	✓
2PCS	TAILLAMPS @\$950.00	one	580 x 2 = 1160	\$1,900.00	✓
1PC	REAR BUMPER	20 / se	985	\$1,415.10	✓
2PCS	REAR BUMPER SIDE RETAINERS @\$45.00	11		\$90.00	X
2PCS	REAR BUMPER REFLECTORS @\$75.00	11		\$150.00	X
2PCS	REAR BUMPER SIDE COVERS @\$111.00	new o / s twi		\$222.00	126
2PCS	REAR BUMPER INNER SPONGES @\$150.00	new o / s torn	148.00	\$300.00	126
1PC	REAR END PANEL	20 / surf	615.00	\$755.20	✓
1PC	REAR END PANEL TOP GARNISH	twi		\$248.70	✓
1PC	REAR END PANEL ANTENNA SENSOR	11		\$108.90	X
2PCS	REAR END PANEL SIDE EXTENSION PANELS @\$285.00	11		\$570.00	X
1PC	REAR EXHAUST	11		\$688.20	X
1PC	REAR FLOOR PANEL TOP BOARD	11		\$544.10	X
1PC	REAR FLOOR PANEL	11		\$1,140.20	X
1PC	REAR FLOOR PANEL TOOLS TRAY	twi / one	481.20	\$652.30	✓
2PCS	REAR FENDER INNER TRIM BOARDS @\$690.00	de / torn	455 x 2 = 910	\$1,380.00	✓
1PC	REAR FENDER	11		\$1,155.20	X
				\$15,143.60	

(202)

S.NETT

1PC	REAR WINDSCREEN SEALANT	new		\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	new		\$50.00	20
1SET	REAR BUMPER REVERSE SENSOR	svc		\$280.00	X
1SET	TAILGATE INNER TRIM BOARD CLIPS	new		\$50.00	40
1SET	REAR BUMPER CLIPS	new		\$60.00	30
1PC	REAR BUMPER LOWER SPOILER	20 / se		\$900.00	600
1PC	REAR END PANEL SEALANT	new		\$50.00	✓
1SET	REAR FLOOR PANEL INSULATOR	11		\$200.00	X

TO CHECK WIRING *refix* \$50.00 20
TO DISMANTLE & REPLACED REVERSE SENSOR \$80.00 30

TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	60
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO SPRAY RUST PROOFING	\$100.00	50
TO RESET DIAGNOSTIC & REPROGRAMME SYSTEM	^^ \$120.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	600
TO PUTTY & SPRAY PAINTING	\$1,800.00	800
TOTAL	\$21,103.60	

LKK Auto Consultants hereby notify the Repairer of the following:

- Temporary before/after spray painting
- To display damaged parts, if necessary
- All prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be reapproved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

P - 7380.7
2021
5904.56
980
1740
2424.56
20
6738