

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ SMR 24090041/Unp3**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD (TP) / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKR 5293Mat Workshop m/s precise

of \_\_\_\_\_

Insured: SHE 190H

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: \$10k.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 221G  
Vehicle: IN / OUTDate: \_\_\_\_\_ Person Contacted: LTA 6395Veh No: SKR 5293M Yr Regn: 12/02/15Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or (M) /Make: motor 3 c.c. 1496Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 25925 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: IM6BM 42A8 F0167230Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/08/24 D.O.I. 11/09/24

Survey held at \_\_\_\_\_

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orMS Rear  
The U/C / Chassis frame / Body Structure affected due to collision.Date / Time Action / Instruction 20, 13k.

21/10/24 2/5 \$2200 is home yan hong  
(Red. \$4978.48, 69%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ )

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$ )

☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

TOTAL

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	221G
Vehicle Details	
Vehicle No.:	SKR5293M
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Sep 2024
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	P520255332
Chassis No.:	JM6BM42A8F0167230
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,624.00
Original Registration Date:	12 Feb 2015
First Registration Date:	12 Feb 2015
Transfer Count:	3
Actual ARF Paid:	\$7,624.00 3812
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Feb 2025
PARF Rebate Amount:	\$3,812.00
Intended COE Rebate Details	
COE Expiry Date:	11 Feb 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$62,002.00
COE Rebate Amount:	\$2,583.00
Total Rebate Amount:	\$6,395.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 11 Sep 2024

OK

Home Used Cars Listing

All Category

Filter

Search

Save Search



2015 X

36 Vehicles

Car Make

Car Model

Price Range

Depreciation

2015

Mileage



Mazda 3 1.5A Sunroof **\$13,300** \$14,130 /yr 18-Jun-2015 95,000 km 3 Owners  
Instl. \$1,183 /mth

Buy a good car important right? This one same like touch Toto. Really no horse run. For freedom yr mind, can go yr wshop confirm, go STA can also. Sell cheap, no agmt fee, no admin, no got nothing. No more loan so immediate can transfer. Aircon cold like in Switzerland. Say good no use, free come and see, sure buy one. The best, really no bluff. Body sell at least \$2600, low low depre. Fix pricing to go



DIRECT OWNER



Mazda 3 1.5A Sunroof **\$10,800** N.A 11-Feb-2015 130,000 km 2 Owners  
Instl. \$2,536 /mth

Non PHV unit. Comfortable and economical car. priced to sell. owner upgraded due to family. Car regularly maintain and in good working condition. Call us for a viewing now! Consignment unit. Viewing by appointment only! Option to convert to renew Coe. Posted 10-Sep-2024

☐ Compare

Mazda 3 1.5A Deluxe Sunroof **\$19,200** \$12,280 /yr 14-Oct-2015 179,000 km 2 Owners  
Instl. \$1,148 /mth

2 owners non phv, high specs sporty unit, spacious cabin and boot, excellent fuel efficiency, well maintained inside out, no repair needed, ideal for short term drive or COE renewal! Genuine and transparent dealing backed by positive reviews, buy with assurance! 100% loan available, trade in welcome. Contact us now before it's sold!

Posted 09-Sep-2024

☐ Compare

Mazda 3 1.5A Deluxe Sunroof **\$20,800** \$13,220 /yr 30-Oct-2015 66,600 km 1 Owner  
Instl. \$1,243 /mth

Guarantee Buy Back \$7,800 By Oct 2025, 1 Owner, Low Mileage Done Only 66,600Km, Serviced By Agent, Fuel Efficient Yet Reliable Car. 100% Loan & Balloon Scheme Available, Ex Bankruptcy And Bad Credit Welcome, High Trade In. Please Contact Our Friendly Sales Consultant For A Viewing Appointment Before It's Gone. Faster Auto Trading | Posted 09-Sep-2024

☐ Compare

Compare

# PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

14-10-24

Accident Date : 30-08-2024

OUR REF : SKR 5293M/T/24(SJE)

PRECISE CAR RENTAL PTE LTD

1 Kaki Bukit Ave 6

#02-33

Singapore 417883

Attn : Marcus  
Date in/out: 10/09/24 to 13/09/24

not Authorised  
on  
meray  
11/9/24  
2/5 \$ 2200  
3 days.  
telephone. How up -

ESTIMATE BILL ON VEH. NO : SKR 5293M

VEHICLE MODEL : MAZDA 3

CHASSIS NO : JM6BM42A8F0167230

## LIST ITEM

Rear Bumper		cut/trim	1,074.80	
Rear Bumper Side Retainer LH		one	53.50	
Rear Bumper Clips	10pcs @ 5.00	new	50.00	
Rear Bumper Splash Shield LH		trim	82.40	
Rear Fender		R	1,174.20	X
Rear Windscreen Clips	14pcs @ 4.00	11	56.00	X
Rear Windscreen Glass Moulding		11	110.40	X
Rear Knuckle Arm - LH		11	654.00	X
Rear Wheel Bearing Hup LH		Daye	415.00	
Rear Control Arm		11	186.00	X
Rear Upper Arm		11	435.80	X
Rear Absorber		11	354.00	X
Sport Rim Assy		cut/repair	1,102.00	5505/n
			5,748.10	
	Less Discount 20%:		1,149.62	
			4,598.48	

## SPECIAL NETT ITEM

Rear Windscreen Glass Sealant 11 60.00 X

## LABOUR CHARGE

To check & adjust computer wheel alignment	60	120.00
To remove & refix rear windscreen glass	11 X	180.00
To remove & refix reverse sensor	30	120.00
To respray affected areas	11 X	550.00
To remove & refix rear LH wheel bearing hup, control arm & upper arm	100	380.00
To renew damaged parts, straighten & repair and aligned all parts	280	550.00
To remove & refix rear LH sport rim & contact wheel balancing	11 X	120.00
To putty & spray painting	400	500.00
		<hr/>

GST 9% :           
TOTAL AMOUNT : 7178.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1675-7  
202  
1342.86  
550  
810  
2765.86  
202  
2208