



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2400522

INV Date : 05-09-2024

Reference CS3/SMR24090043/Rnh3e2

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SNP 4421S
Insured Veh. SG 5533J
Claim No. BUS/08/24/5050
Policy No.
Accident Date 28/08/2024
Inspection Date 03/09/2024

Description	Amount
Pre-Repair Survey	128.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Ref: CS3/SMR24090043/Rnh3e2 Date: 05/09/2024 Code: SMR
---	--

1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	SG 5533J	Veh. Inspected	SNP 4421S
Policy No.	-	Coverage	0
Claim No.	BUS/08/24/5050	Excess	\$0.00
Assign From	HUA YEN	Assign Date	02/09/2024

2. Vehicle Details

Make & Model	PORSCHE PANAMERA V6 ED	C.C	3605
Engine No.	011075	Year of Reg.	29/01/2016
Chassis No.	WP0ZZZ97ZGL001849	Colour	BLACK
Odometer	106440 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	255/40Z R20	PIRELLI	6
L/H Front Tyre	255/40Z R20	PIRELLI	6
R/H Rear Tyre	255/40Z R20	PIRELLI	6
L/H Rear Tyre	255/40Z R20	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

5. General Information

Accident Date	28/08/2024	Inspection Date	03/09/2024 (15:34)
Survey held at	HOE KENG MOTOR SERVICE & TRADING BLK 7 PIONEER ROAD NORTH #01-43 SINGAPORE 628459		


5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00-\$7,000.00

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days

PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 5 of 5)

PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 4 of 14)

PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 7 of 14)

PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 8 of 14)

PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S




PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 14 of 14)

PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S

