

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2400522

INV Date : 05-09-2024

Reference CS3/SMR24090043/Rnh3e2

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SNP 4421S
Insured Veh. SG 5533J
Claim No. BUS/08/24/5050
Policy No.
Accident Date 28/08/2024
Inspection Date 03/09/2024

Description	Amount
Pre-Repair Survey	128.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		Ref:	CS3/SMR24090043/Rnh3e2	
		Date:	05/09/2024	
		Code:	SMR	
1. Policy Particulars :- PRE-REPAIR SURVEY				
Insured Veh.	SG 5533J	Veh. Inspected	SNP 4421S	
Policy No.	-	Coverage	0	
Claim No.	BUS/08/24/5050	Excess	\$0.00	
Assign From	HUA YEN	Assign Date	02/09/2024	
2. Vehicle Details				
Make & Model	PORSCHE PANAMERA V6 ED	C.C	3605	
Engine No.	011075	Year of Reg.	29/01/2016	
Chassis No.	WP0ZZZ97ZGL001849	Colour	BLACK	
Odometer	106440 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	255/40Z R20	PIRELLI	6	
L/H Front Tyre	255/40Z R20	PIRELLI	6	
R/H Rear Tyre	255/40Z R20	PIRELLI	6	
L/H Rear Tyre	255/40Z R20	PIRELLI	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
5. General Information				
Accident Date	28/08/2024	Inspection Date	03/09/2024 (15:34)	
Survey held at	HOE KENG MOTOR SERVICE & TRADING BLK 7 PIONEER ROAD NORTH #01-43 SINGAPORE 628459			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00-\$7,000.00				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S



PHOTOGRAPHS FOR VEHICLE NO. : SNP 4421S

