


PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P




PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P





PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P






PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P




PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P




PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P




PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P





PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P




PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P




PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P





PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P




PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,

Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

INSPECTION PHOTOS (Page 30 of 31)

PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P



PHOTOGRAPHS FOR VEHICLE NO. : SLD 8033P

