

T K LEE AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47
 AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*Not Authorized
 du
 moras
 3/9/24
 repair sum \$4900
 4 days.*

Vehicle No.: SKP40U
 Model : AUDI A5

PARTICULAR		UNIT PRICE	AMOUNT
LIST PRICE		SS	SS
1	1 REAR BUMPER	1,995.75	1,995.75
2	2 REAR BUMPER PDC SENSOR	260.00 MS 312.75	627.50
3	1 REAR BUMPER DIFUSSER	648.12	648.12
4	1 REAR BUMPER REFLECTOR -LH	110.22	110.22
5	1 REAR BUMPER REINFORCEMENT	1,055.90	1,055.90
6	2 REAR BUMPER SIDE RETAINERS - R/L	115.00	230.00
7	1 REAR END PANEL	1,150.91	1,150.91
8	1 REAR EXHAUST CHROME TRIM -LH	611.45	611.45
9	1 REAR EXHAUST CHROME TRIM BRACKET	251.63	251.63
10	1 REAR FOOT - ACTIVATED SENSOR	281.93	281.93
11	1 TAILGATE	2,889.63	2,889.63
12	1 TAILGATE BADGE	181.66	181.66
13	1 TAILGATE EMBLEM 'A5'	99.01	99.01
14	1 TAILGATE LAMP -LH	631.55	631.55
15	1 TAILLAMP -LH	831.11	831.11
			11,596.37
LESS 5% 102			579.82
			11,016.55
SPECIAL NETT ITEMS			
1	1 (SET) REAR BUMPER CLIP		60.00
2	1 (SET) REAR BUMPER SIDE HOLDER		80.00
			140.00
LABOUR CHARGES :			
1	TO CHECK REAR ELECTRICAL WIRING		50.00
2	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR		120.00
3	TO TUFF KOTE		100.00
4	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		1,080.00
5	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS		900.00
TOTAL:			2,250.00

*P- 4911.44
 102
 4420.30
 40
 1020
 5480.30*

TOTAL AMOUNT : 13,406.55