



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS GREAT AMERICAN INSURANCE COMPANY	Ref:	CS/GAI24090046/Unp3
3 TEMASEK AVENUE	Date:	19/09/2024
#16-01 CENTENNIAL TOWER	Code:	GAI
SINGAPORE 039190		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YQ 8888S	Veh. Inspected	SCK 6262C
Policy No.	-	Coverage	0
Claim No.	CLMOMVC000004535	Excess	\$0.00
Assign From	JOCELYN TENG	Assign Date	03/09/2024

2. Vehicle Details

Make & Model	BMW 523I A	C.C	2497
Engine No.	08767877N52B25AF	Year of Reg.	01/11/2011
Chassis No.	WBAFP32030C868218	Colour	GREY
Odometer	197723 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/40ZR19	MICHELIN	7
L/H Front Tyre	245/40ZR19	MICHELIN	7
R/H Rear Tyre	275/35ZR19	MICHELIN	7
L/H Rear Tyre	275/35ZR19	MICHELIN	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/08/2024	Inspection Date	03/09/2024
Survey held at	3 MOTORWERKZ CONCEPT PTE LTD - 25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days