

3 MOTORWERKZ CONCEPT PTE LTD

VEHICLE No: SCK 6262C

BMW 523

NETT

not Authorized
mercad
3/9/24
2/s # 12,200
Chapman
5 days

1PC	BOOTLID	DD/Bent	\$1,870.60	✓
1PC	BOOTLID REFLECTOR N/S	SC	\$302.00	X
1PC	BOOTLID INNER LOCK	SC	\$345.00	X
1PC	BOOTLID WEATHERSTRIP	11	\$290.00	X
1PC	REAR BUMPER	DD/Torn	\$1,681.50	✓
1PC	REAR BUMPER BEAM	R	\$615.00	X
1PC	REAR BUMPER TOP RETAINER	Che	\$209.60	✓
1PC	REAR BUMPER PDC SENSOR N/S	malfunction	\$198.00	✓
1PC	REAR BUMPER KICKING SENSOR	11	\$288.00	X
1PC	REAR BUMPER SIDE RETAINER	11	\$162.00	X
1SET	REAR BUMPER CLIPS	11	\$50.00	✓
1PC	REAR END PANEL	DD/Bent	\$1,100.80	✓
1PC	TAILLAMP N/S	11	\$615.00	✓
1PC	BONNET	11	\$2,102.00	X
1PC	FRONT BUMPER	DD/De	\$1,480.50	✓
1PC	FRONT BUMPER BEAM	R	\$745.00	X
1PC	FRONT BUMPER SPONGE	Torn	\$168.00	✓
1PC	FRONT BUMPER SIDE RETAINER	11	\$162.00	X
2PCS	FRONT GRILLES @\$145.00	11	\$290.00	✓
1PC	HEADLAMP N/S	one	\$2,896.40	✓
1PC	HEADLAMP O/S	one	\$2,896.40	✓
1PC	FRONT SUPPORT PANEL	R	\$541.00	X
1PC	FRONT SUPPORT NOSE GARNISH	Torn	\$302.00	✓
1PC	CONDENSER	11	\$890.00	X
1PC	RADIATOR	11	\$1,100.00	X
			\$21,300.80	

(570)

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$80.00	30
TO TRANSFER BOOTLID MECHANISM	\$100.00	60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	60
TO DIAGNOSTIC & REPROGRAMME SYSTEM	\$180.00	X
TO SPRAY RUST PROOFING	\$100.00	50
TO REFILL AIR CON GAS	\$100.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	1000
TO PUTTY & SPRAY PAINTING	\$2,200.00	1000
TOTAL	\$26,030.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-13758-80
52
1307086
2230
1530086
202
12240