

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 6387P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	3,200.00	2,600.00
1	REAR LH FENDER GARNISH	TO REPAIR SEE LABOUR	2,200.00	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	150.00	-
1	REAR ENGINE COVER	DENTED	2,800.00	2,400.00
2	REAR ENGINE COVER HINGES	NOT NECESSARY	800.00	-
1	REAR ENGINE COVER LOCK	NOT NECESSARY	410.00	-
1	REAR ENGINE COVER LOCK CATCH	NOT NECESSARY	120.00	-
1	REAR TAIL LAMP LH	NOT NECESSARY	955.60	-
1	REAR SIGNAL LAMP LH	NOT NECESSARY	550.00	-
	LESS 10% DISCOUNT		-1,118.56	-500.00
			10,067.04	4,500.00
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLPS (SN)	NOT NECESSARY	200.00	-
1	SET REAR LH FENDER GARNISH CLIPS (SN)	NOT NECESSARY	150.00	-
1	REAR ENGINE COVER STICKER (SN)	NECESSARY	400.00	300.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
1	REAR NUMBER PLATE BRACKET (SN)	NOT NECESSARY	35.00	-
1	REAR 60KM (SN)	NOT NECESSARY	20.00	-
			850.00	300.00
	LABOUR			
	TO DISMANTLE DAMAGED PARTS, STRAIGHTEN & WELDING. INCLUSIVE OF THE REPAIR OF REAR LH FENDER GARNISH.		2,000.00	600.00
	TO SPRAY PAINTING.		1,000.00	600.00
	TO RESEAL ANTI RUST.		100.00	40.00
	TO CHECK WIRING.		100.00	30.00
			3,200.00	1,270.00
	GRAND TOTAL		14,117.04	6,070.00

Report Ref No. CS/INC24090050/Aqh3m4(N)



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,800.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. CS/INC24090050/Aqh3m4(N)

TOTAL FOR SPARE PARTS: \$10,917.04 \$ 4,800.00 TOTAL FOR LABOUR: \$ 3,200.00 \$ 1,270.00 TOTAL REPAIR COST: \$14,117.04 \$ 6,070.00

XX.X.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.