

Xiao Chen

ESTIMATE OF REPAIR

Veh# : PC6387P

Model: GOLDEN DRAGON
24/11/2017

Accident Date : 28/8/2024

Location : jurong gateway

3P: SKT8345S (INCOME)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Dehnd</i>	3200.00	<i>2600</i>	
2	1pc	Rear bumper clips <i>Ren</i>		200.00	<i>+</i>
3	1pc	Rear Lh fender garnish <i>Ren</i>	2200.00	<i>+</i>	
4	1 set	Rear Lh fender garnish clips <i>Ren</i>		150.00	<i>+</i>
5	1pc	Rear bumper reflector LH <i>Ren</i>	150.00	<i>+</i>	
6	1pc	Rear engine cover <i>Dented</i>	2800.00	<i>2400</i>	
7	2pcs	Rear engine cover hinges <i>Ren</i>	800.00	<i>+</i>	
8	1pc	Rear engine cover lock <i>Ren</i>	410.00	<i>+</i>	
9	1pc	Rear engine cover lock catch <i>Ren</i>	120.00	<i>+</i>	
10	1pc	Rear engine cover sticker <i>Ren</i>		400.00	<i>300</i>
11	1pc	Rear tail lamp LH <i>Ren</i>	955.60	<i>+</i>	
12	1pc	Rear signal lamp LH <i>Ren</i>	550.00	<i>+</i>	
13	1pc	Rear number plate <i>Ren</i>		45.00	<i>+</i>
14	1pc	Rear number plate bracket <i>Ren</i>		35.00	<i>+</i>
15	1pc	Rear 60km <i>Ren</i>		20.00	<i>+</i>
<i>5000</i> <i>SN: 300</i> Sub-Total:			11,185.60	850.00	0.00
<i>4500</i>			10%	0%	10%
After Less %:			10,067.04	850.00	0.00
Labour					
1		To dismantle damaged parts, straighten & welding.		2,000.00	<i>600</i>
2		To spray painting.		1,000.00	<i>600</i>
3		To reseal anti rust		100.00	<i>40</i>
4		To check wiring.		100.00	<i>30</i>
Sub-Total:				3,200.00	
Total:				14,117.04	
After Less 20%:				11,293.63	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- Chan San Choon
Director, *Witnessed by Repairer*
DipEng, AAE MIMI, MSAE(Aust)

total: 6070

h/s: A-8K ✓

Adnan Ly

h/s 19/09/24

04 Days

