

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail: jlperfectautowork@gmail.com



DATE : 26.08.2024

TO	: INDIA INTERNATIONAL	MOTOR CLAIMS DEPTS
VEHICLE NO	: SLQ9490C	
MODEL	: BMW 420i	
DATE OF ACCIDENT	: 17.08.2024	
TIME OF ACCIDENT	: 11:40 HOURS	

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Defect</i>	1	\$ 1,650.85	\$ 1,650.85
2	REAR BUMPER CENTER MOUDLING <i>Cut</i>	1	\$ 381.15	\$ 381.15
3	REAR BUMPER REFLECTOR <i>Cracked</i>	2	\$ 95.00	\$ 190.00
4	REAR BUMPER TOWING COVER <i>New</i>	1	\$ 75.50	\$ 75.50
5	REAR BUMPER SENSOR <i>2 pieces damaged</i>	4	\$ 236.85	\$ 947.40
6	REAR BUMPER SENSOR HOLDER <i>New</i>	4	\$ 62.05	\$ 248.20
7	REAR BUMPER SENSOR WIRE HARNESS <i>New</i>	1	\$ 1,754.60	\$ 1,754.60
8	REAR BUMPER TOP CENTER COVER GARNISH <i>Cracked</i>	1	\$ 197.95	\$ 197.95
9	REAR BUMPER REINFORCEMENT <i>Defect</i>	1	\$ 774.25	\$ 774.25
10	REAR BUMPER REINFORCEMENT COVER GARNISH <i>Cracked</i>	1	\$ 168.45	\$ 168.45
11	REAR BUMPER TOP BEAM <i>Cracked</i>	1	\$ 395.00	\$ 395.00
12	REAR BUMPER SIDE BRACKET (PLASTIC) <i>New</i>	2	\$ 281.50	\$ 563.00
13	TAIL LAMP <i>RH cracked</i>	2	\$ 594.25	\$ 1,188.50
14	TAIL LAMP SIDE GARNISH <i>New</i>	2	\$ 39.45	\$ 78.90
15	REAR FENDER INNER TRIM RH <i>New</i>	2	\$ 764.65	\$ 1,529.30
16	BOOT LID <i>Repair</i>	1	\$ 1,692.50	\$ 1,692.50
17	BOOT LID EMBLEM '420i' <i>3 New</i>	1	\$ 97.60	\$ 97.60
18	BOOT LID LOGO	1	\$ 69.55	\$ 69.55
19	BOOT LID TOP LOCK <i>New</i>	1	\$ 91.55	\$ 91.55
20	BOOTLID SMART OPENER MODULE <i>Cracked</i>	1	\$ 468.85	\$ 468.85
21	BOOT LID WEATHERSTRIP <i>cut</i>	1	\$ 215.35	\$ 215.35
22	BOOT LID SENSOR DETECTOR <i>New</i>	1	\$ 414.75	\$ 414.75

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLQ9490C**
 MODEL : **BMW 420i**
 DATE OF ACCIDENT : **17.08.2024**
 TIME OF ACCIDENT : **11:40 HOURS**

23	BOOT LID LOWER LOCK <i>Hand</i>	1	\$ 376.45	\$ 376.45	✓
24	REAR END PANEL <i>Dented</i>	1	\$ 871.35	\$ 871.35	✓
25	REAR END PANEL TOP GARNISH <i>could</i>	1	\$ 195.00	\$ 195.00	✓
26	REAR FLOOR PANEL TOP BOARD <i>3 feet</i>	1	\$ 683.55	\$ 683.55	+
27	REAR EXHAUST INSULATOR <i>3 feet new</i>	1	\$ 286.00	\$ 286.00	+

7219.75
6858.76

TOTAL PRICE \$ 15,605.55
 LESS 5% \$ 780.28
SUB TOTAL PRICE \$ 14,825.27

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PALTE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
4	TAIL LAMP CLIP (SET)	1	\$ 60.00	\$ 60.00	+
5	TAIL LAMP SIDE GARNISH CLIP (SET) <i>1/2</i>	1	\$ 50.00	\$ 50.00	+
6	BOOT LID SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
7	BOOT LID INSULATOR CLIP (SET)	1	\$ 80.00	\$ 80.00	+
8	REAR FENDER INNER TRIM CLIPS (SET)	1	\$ 80.00	\$ 80.00	+
9	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 250.00	\$ 250.00	60
10	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	20
11	REAR WINDSCREEN SEALANT <i>3 feet</i>	1	\$ 80.00	\$ 80.00	40
12	REAR WINDSCREEN INNER SHIELD <i>3 feet</i>	1	\$ 80.00	\$ 80.00	40

190

TOTAL \$ 990.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	700
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	700
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 380.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 380.00	60

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLQ9490C**
 MODEL : **BMW 420i**
 DATE OF ACCIDENT : **17.08.2024**
 TIME OF ACCIDENT : **11:40 HOURS**

6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 100.00	50
8	TRANSFER BOOTLID MECHANISM	\$ 150.00	60
9	RESET BOOD LID AUTO SYSTEM	\$ 350.00	X
10	RESET BRAKE SMART OPEN MODULE SENSOR	\$ 280.00	120
10	REMOVE AND REFIX REAR VIDEO RECORDER	\$ 80.00	50
11	REMOVE AND REFIX REAR. WINDSCREEN GLASS	\$ 120.00	✓
12	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 1,200.00	X 200.

TOTAL \$ 6,720.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 15,815.27
 TOTAL LABOUR COST : \$ 6,720.00
 TOTAL REPAIR COST : \$ 22,535.27

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP: 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian
 1/s 28/08/24.
 06 days

total: 9248.76
 4/s 734K

74K

2200