

ASSIGNMENT

From: _____ Date: _____

Estn: _____

OD / TP RES / CD RES / EVA / INV / MV

To In: _____ Vehicle No: _____

at W: _____

of _____

Insured: _____

Policy: _____

Claims: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ9490C Yr Regn: 2017 July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 420i C.D. 1998

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 83482 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA4H32080 BH1118

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/35R19

R: 255/35R19

BS / DUN / EXNOVA / GY / FS / IZA / MIG / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 06 mm

Rear R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____ D.O.I. 28/08/24

Survey held at JL Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 111

COE Expiry: _____

Estimate given during: Yes (✓)

1st Survey: No ()

MV: _____

PV: _____

Nett: _____

590F.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Inve (\$)

Survey Fee:

Transportation:

3 + R8 \$1

Photos

Others

Report Form: _____

Report Form: _____

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 26.08.2024

TO	: INDIA INTERNATIONAL	MOTOR CLAIMS DEPTS
VEHICLE NO	: SLQ9490C	
MODEL	: BMW 420i	
DATE OF ACCIDENT	: 17.08.2024	
TIME OF ACCIDENT	: 11:40 HOURS	

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Delin d</i>	1	\$ 1,650.85	\$ 1,650.85
2	REAR BUMPER CENTER MOUDLING <i>Cut</i>	1	\$ 381.15	\$ 381.15
3	REAR BUMPER REFLECTOR <i>Cut</i>	2	\$ 95.00	\$ 190.00
4	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 75.50	\$ 75.50
5	REAR BUMPER SENSOR <i>2 pieces damaged</i>	4	\$ 236.85	\$ 947.40
6	REAR BUMPER SENSOR HOLDER <i>new</i>	4	\$ 62.05	\$ 248.20
7	REAR BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 1,754.60	\$ 1,754.60
8	REAR BUMPER TOP CENTER COVER GARNISH <i>Cut</i>	1	\$ 197.95	\$ 197.95
9	REAR BUMPER REINFORCEMENT <i>Defect</i>	1	\$ 774.25	\$ 774.25
10	REAR BUMPER REINFORCEMENT COVER GARNISH <i>Cut</i>	1	\$ 168.45	\$ 168.45
11	REAR BUMPER TOP BEAM <i>Cut</i>	1	\$ 395.00	\$ 395.00
12	REAR BUMPER SIDE BRACKET (PLASTIC) <i>new</i>	2	\$ 281.50	\$ 563.00
13	TAIL LAMP <i>RH cut</i>	2	\$ 594.25	\$ 1,188.50
14	TAIL LAMP SIDE GARNISH <i>new</i>	2	\$ 39.45	\$ 78.90
15	REAR FENDER INNER TRIM RH <i>new</i>	2	\$ 764.65	\$ 1,529.30
16	BOOT LID <i>Repair</i>	1	\$ 1,692.50	\$ 1,692.50
17	BOOT LID EMBLEM '420i' <i>3 new</i>	1	\$ 97.60	\$ 97.60
18	BOOT LID LOGO	1	\$ 69.55	\$ 69.55
19	BOOT LID TOP LOCK <i>new</i>	1	\$ 91.55	\$ 91.55
20	BOOTLID SMART OPENER MODULE <i>Cut</i>	1	\$ 468.85	\$ 468.85
21	BOOT LID WEATHERSTRIP <i>cut</i>	1	\$ 215.35	\$ 215.35
22	BOOT LID SENSOR DETECTOR <i>new</i>	1	\$ 414.75	\$ 414.75

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLQ9490C**
 MODEL : **BMW 420i**
 DATE OF ACCIDENT : **17.08.2024**
 TIME OF ACCIDENT : **11:40 HOURS**

23	BOOT LID LOWER LOCK <i>Hand</i>	1	\$ 376.45	\$ 376.45	<i>✓</i>
24	REAR END PANEL <i>Dented</i>	1	\$ 871.35	\$ 871.35	<i>✓</i>
25	REAR END PANEL TOP GARNISH <i>cauld</i>	1	\$ 195.00	\$ 195.00	<i>✓</i>
26	REAR FLOOR PANEL TOP BOARD <i>3 rest</i>	1	\$ 683.55	\$ 683.55	<i>+</i>
27	REAR EXHAUST INSULATOR <i>3 rest New</i>	1	\$ 286.00	\$ 286.00	<i>+</i>

TOTAL PRICE \$ 15,605.55
 LESS 5% \$ 780.28
SUB TOTAL PRICE \$ 14,825.27

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PALTE <i>New</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
2	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
4	TAIL LAMP CLIP (SET)	1	\$ 60.00	\$ 60.00	<i>+</i>
5	TAIL LAMP SIDE GARNISH CLIP (SET) <i>1 stop</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
6	BOOT LID SEALANT <i>New</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
7	BOOT LID INSULATOR CLIP (SET)	1	\$ 80.00	\$ 80.00	<i>+</i>
8	REAR FENDER INNER TRIM CLIPS (SET)	1	\$ 80.00	\$ 80.00	<i>+</i>
9	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 250.00	\$ 250.00	<i>60</i>
10	REAR END PANEL TOP GARNISH CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	<i>20</i>
11	REAR WINDSCREEN SEALANT <i>3 New</i>	1	\$ 80.00	\$ 80.00	<i>40</i>
12	REAR WINDSCREEN INNER SHIELD	1	\$ 80.00	\$ 80.00	<i>40</i>

TOTAL \$ 990.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	<i>700</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>700</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 380.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 380.00	<i>60</i>

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLQ9490C**
 MODEL : **BMW 420i**
 DATE OF ACCIDENT : **17.08.2024**
 TIME OF ACCIDENT : **11:40 HOURS**

6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 100.00	50.
8	TRANSFER BOOTLID MECHANISM	\$ 150.00	60
9	RESET BOOD LID AUTO SYSTEM	\$ 350.00	X
10	RESET BRAKE SMART OPEN MODULE SENSOR	\$ 280.00	120.
10	REMOVE AND REFIX REAR VIDEO RECORDER	\$ 80.00	50
11	REMOVE AND REFIX REAR. WINDSCREEN GLASS	\$ 120.00	✓
12	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 1,200.00	X 200.

TOTAL \$ 6,720.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 15,815.27
 TOTAL LABOUR COST : \$ 6,720.00
 TOTAL REPAIR COST : \$ 22,535.27

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP: 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian C
1/s 28/08/24.
06 Days