

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE :	_____	Vehicle Nos :	SLJ 6111D
Date of Survey :	_____	Made :	Honda
Date of ReSurvey:	_____	Model :	Vezel 1.5X CVT
Contacts :	_____	Chassis No :	RU11208992

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount:	_____	Working Day:	_____
---------	-------	--------------	-------

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bumper <i>Del d</i>	1	\$ 797.90	\$ ✓ 797.90
2	Rear Bumper Side Retainer RH <i>gap</i>	1	\$ 34.00	\$ + 34.00
3	Rear Bumper Side Retainer LH <i>gap</i>	1	\$ 34.00	\$ + 34.00
4	Rear Bumper Reflector RH <i>could</i>	1	\$ 161.00	\$ ✓ 161.00
5	Rear Bumper Reflector LH <i>new</i>	1	\$ 161.00	\$ x 161.00
6	Rear Bumper Side RH <i>torn</i>	1	\$ 217.60	\$ ✓ 217.60
7	Rear Bumper Side LH <i>new</i>	1	\$ 217.60	\$ + 217.60
8	Rear Bumper Centre Lower Cover <i>torn</i>	1	\$ 254.00	\$ ✓ 254.00
9	Rear Tailgate <i>dent</i>	1	\$ 1,393.40	\$ <i>new</i> 1,393.40
10	Rear Tailgate Lock Assembly <i>damaged</i>	1	\$ 187.40	\$ ✓ 187.40
11	Rear Tailgate Lock Catch <i>new</i>	1	\$ 76.80	\$ + 76.80
12	Rear Tailgate Hinge RH <i>gap</i>	1	\$ 55.00	\$ + 55.00
13	Rear Tailgate Hinge LH <i>gap</i>	1	\$ 55.00	\$ + 55.00
14	Rear Tailgate Damper RH <i>new</i>	1	\$ 132.65	\$ + 132.65
15	Rear Tailgate Damper LH <i>new</i>	1	\$ 132.65	\$ + 132.65
16	Rear Tailgate Outer Garnish with Moulding <i>new</i>	1	\$ 220.00	\$ + 220.00
17	Rear Emblem <i>new</i>	1	\$ 39.70	\$ + 39.70
18	Rear Tailgate "Vezel" Emblem <i>new</i>	1	\$ 58.00	\$ ✓ 58.00
19	Rear Tailgate Weatherstrip <i>new</i>	1	\$ 401.70	\$ x 401.70
20	Rear Tailgate Number Plate Lamp RH <i>gap</i>	1	\$ 48.00	\$ + 48.00
21	Rear Tailgate Number Plate Lamp LH <i>gap</i>	1	\$ 48.00	\$ x 48.00
22	Rear Tailgate Reflector Lamp RH <i>cut</i>	1	\$ 389.20	\$ ✓ 389.20
23	Rear Tailgate Reflector Lamp LH <i>new</i>	1	\$ 389.20	\$ x 389.20
24	Rear Tailgate Inner Handle <i>new</i>	1	\$ 46.00	\$ + 46.00
25	Rear Tailgate Inner Trim Board <i>could</i>	1	\$ 388.60	\$ ✓ 388.60
26	Rear Tailgate Windscreen Moulding RH <i>gap</i>	1	\$ 137.40	\$ ✓ 137.40
27	Rear Tailgate Windscreen Moulding LH <i>gap</i>	1	\$ 137.40	\$ ✓ 137.40

28	Rear Tailgate Windscreen Moulding Lower <i>new</i>	1	\$ 81.70	\$ 81.70	
29	Rear Tailgate Wiper Motor <i>new</i>	1	\$ 512.00	\$ 512.00	
30	Rear Tailgate Stopper RH <i>new</i>	1	\$ 18.00	\$ 18.00	
31	Rear Tailgate Stopper LH <i>new</i>	1	\$ 18.00	\$ 18.00	
32	Rear End Panel <i>Dented</i>	1	\$ 857.20	\$ 857.20	595
33	Rear End Panel Top Garnish <i>Dented</i>	1	\$ 135.00	\$ 135.00	
34	Rear Spare Tyre Panel <i>new</i>	1	\$ 1,108.80	\$ 1,108.80	
35	Rear Spare Tyre Panel Top Board <i>new</i>	1	\$ 168.00	\$ 168.00	
36	Rear Spare Tyre Panel Tools Box Sponge <i>new</i>	1	\$ 310.00	\$ 310.00	
37	Rear Taillamp Assembly RH <i>new</i>	1	\$ 502.40	\$ 502.40	474
38	Rear Taillamp Lower Bracket RH <i>new</i>	1	\$ 32.60	\$ 32.60	
39	Rear Taillamp Assembly LH <i>new</i>	1	\$ 502.40	\$ 502.40	
40	Rear Taillamp Lower Bracket LH <i>new</i>	1	\$ 32.60	\$ 32.60	
41	Rear Fender RH <i>new</i>	1	\$ 1,054.00	\$ 1,054.00	
42	Rear Fender LH <i>new</i>	1	\$ 1,054.00	\$ 1,054.00	
43	Rear Fender Wheel Arch Garnish RH <i>new</i>	1	\$ 235.00	\$ 235.00	
44	Rear Fender Wheel Arch Garnish LH <i>new</i>	1	\$ 235.00	\$ 235.00	
45	Rear Fender Inner Trim Board RH <i>new</i>	1	\$ 548.00	\$ 548.00	399
46	Rear Fender Inner Trim Board LH <i>new</i>	1	\$ 548.00	\$ 548.00	
47	Rear Buzzer <i>new</i>	1	\$ 108.00	\$ 108.00	
48	Rear Smart Key Antenna Sensor <i>new</i>	1	\$ 162.40	\$ 162.40	
49	Rear Exhaust Pipe Assembly <i>new</i>	1	\$ 821.00	\$ 821.00	
50	Rear Exhaust Pipe Assembly Heat Shield <i>new</i>	1	\$ 154.00	\$ 154.00	
51	Rear Exhaust Pipe Mounting <i>new</i>	2	\$ 55.00	\$ 110.00	
Parts Sub Total :				\$ 15,521.30	
20% Discount				\$ 3,104.26	
PARTS TOTAL :				\$ 12,417.04	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate <i>new</i>	1	\$ 50.00	\$ 50.00
2	Rear Bumper Clips - Set <i>new</i>	1	\$ 50.00	\$ 50.00
3	Rear Taillamp Clips - Set <i>new</i>	1	\$ 50.00	\$ 50.00
4	Rear Tailgate Reflector Lamp Clips - Set <i>new</i>	1	\$ 50.00	\$ 50.00
5	Rear End Panel Top Garnish Clips - Set <i>new</i>	1	\$ 50.00	\$ 50.00
6	Rear Fender Inner Shield Clips - Set <i>new</i>	1	\$ 80.00	\$ 80.00
7	Rear Fender Inner Trim Board Clips - Set <i>new</i>	1	\$ 100.00	\$ 100.00
8	Rear Tailgate Sealant <i>new</i>	1	\$ 150.00	\$ 150.00
9	Rear End Panel Sealant <i>new</i>	1	\$ 150.00	\$ 150.00
10	Rear Spare Tyre Panel Sealant <i>new</i>	1	\$ 150.00	\$ 150.00
11	Rear Fender RH Sealant <i>new</i>	1	\$ 150.00	\$ 150.00

12	Rear Fender LH Sealant <i>Abel New</i>	1	\$	150.00	\$ 150.00 <i>+</i> 150.00
13	Rear Tailgate Windscreen Glass Sealant <i>New</i>	1	\$	150.00	\$ 150.00 <i>60</i> 150.00
14	Rear Tailgate Inner Trim Board Clips - Set <i>New</i>	1	\$	50.00	\$ 50.00 <i>30</i> 50.00
15	Rear Tailgate Outer Garnish Clips - Set <i>New</i>	1	\$	50.00	\$ 50.00 <i>+</i> 50.00
16	Rear Fender Wheel Arch Garnish Clips - Set <i>New</i>	1	\$	100.00	\$ 100.00 <i>+</i> 100.00
17	Rear Bumper Reverse Sensor - Set <i>2nd</i>	1	\$	350.00	\$ 350.00 <i>200</i> 350.00
18	Rear Tailgate Reverse Camera <i>New</i>	1	\$	500.00	\$ 500.00 <i>+</i> 500.00
SPECIAL NETT TOTAL :					\$ 2,380.00

Nos.	LABOUR	TOTAL S\$	
1	To Panel Beat, Remove & Refix Parts	\$ 2,400.00 <i>700</i>	2,400.00
2	To Spray Paint Affected Areas	\$ 1,800.00 <i>600</i>	1,800.00
3	Wiring & Bulb Check	\$ 100.00 <i>30</i>	100.00
4	To Remove & Refix Rear Tailgate Windscreen Glass	\$ 150.00 <i>120</i>	150.00
5	To Transfer Tailgate Mechanism	\$ 150.00 <i>60</i>	150.00
6	To Remove & Refix Rear Tailgate Reverse Camera	\$ 150.00 <i>50</i>	150.00
7	To Remove & Refix Rear Bumper Reverse Sensor	\$ 120.00 <i>50</i>	120.00
8	To Remove & Refix Rear Exhaust Pipe	\$ 150.00 <i>+</i>	150.00
9	To Remove & Refix Fuel Tank	\$ 250.00 <i>+</i>	250.00
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 150.00 <i>60</i>	150.00
11	To apply anti rust on affected parts	\$ 150.00 <i>60</i>	150.00
12	To Conduct Water Leak Test	\$ 100.00 <i>+</i>	100.00
13	To Send Diagnostic & Reset Control Unit. Programming & Calibration	\$ 480.00 <i>+</i>	480.00
LABOUR TOTAL :		\$	6,150.00

PARTS TOTAL : \$ 12,417.04
 SPECIAL NETT TOTAL : \$ 2,380.00
 LABOUR TOTAL : \$ 6,150.00
GRAND TOTAL : \$ 20,947.04

Adrian L
2/5 09/09/24
06 Days