

ASSIGNMENT

From: _____ Date: _____
 Estn: Estn
 OD / TP RES / OD RES / EVA / INV / MV
 To in Vehicle No: _____
 at W/O _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vek: _____
 (Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SLJ6111D Yr Regn: 20/6 Dec.
 Type: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Vezel C.D. 1496
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 22580 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: Ru11208992
 Gen. Cond: Good Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: 205/60R16

BS / DUN / EXNOVA / GY / FS / I / IZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Habilead

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 04/09/24
 Survey held at Bitrost
 Des. of Damages: Frt Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>78 Chirn</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV : 391K</u>
	<u>PV : 18.9K</u>
	<u>Nett : 18.1K</u>
	<u>402W</u>

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Inve (\$ _____)

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Report Format:

Report Form: P/LP P/C

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SLJ 6111D**
Made : Honda
Model : Vezel 1.5X CVT
Chassis No : RU11208992

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bumper <i>Del</i>	1	\$ 797.90	\$ 797.90
2	Rear Bumper Side Retainer RH <i>3/4</i>	1	\$ 34.00	\$ 34.00
3	Rear Bumper Side Retainer LH <i>3/4</i>	1	\$ 34.00	\$ 34.00
4	Rear Bumper Reflector RH <i>cut</i>	1	\$ 161.00	\$ 161.00
5	Rear Bumper Reflector LH <i>new</i>	1	\$ 161.00	\$ 161.00
6	Rear Bumper Side RH <i>torn</i>	1	\$ 217.60	\$ 217.60
7	Rear Bumper Side LH <i>new</i>	1	\$ 217.60	\$ 217.60
8	Rear Bumper Centre Lower Cover <i>torn</i>	1	\$ 254.00	\$ 254.00
9	Rear Tailgate <i>Detec</i>	1	\$ 1,393.40	\$ 1,393.40
10	Rear Tailgate Lock Assembly <i>Damaged</i>	1	\$ 187.40	\$ 187.40
11	Rear Tailgate Lock Catch <i>new</i>	1	\$ 76.80	\$ 76.80
12	Rear Tailgate Hinge RH <i>3/4</i>	1	\$ 55.00	\$ 55.00
13	Rear Tailgate Hinge LH <i>3/4</i>	1	\$ 55.00	\$ 55.00
14	Rear Tailgate Damper RH <i>3/4</i>	1	\$ 132.65	\$ 132.65
15	Rear Tailgate Damper LH <i>3/4</i>	1	\$ 132.65	\$ 132.65
16	Rear Tailgate Outer Garnish with Moulding <i>new</i>	1	\$ 220.00	\$ 220.00
17	Rear Emblem <i>new</i>	1	\$ 39.70	\$ 39.70
18	Rear Tailgate "Vezel" Emblem <i>new</i>	1	\$ 58.00	\$ 58.00
19	Rear Tailgate Weatherstrip <i>new</i>	1	\$ 401.70	\$ 401.70
20	Rear Tailgate Number Plate Lamp RH <i>3/4</i>	1	\$ 48.00	\$ 48.00
21	Rear Tailgate Number Plate Lamp LH <i>3/4</i>	1	\$ 48.00	\$ 48.00
22	Rear Tailgate Reflector Lamp RH <i>cut</i>	1	\$ 389.20	\$ 389.20
23	Rear Tailgate Reflector Lamp LH <i>new</i>	1	\$ 389.20	\$ 389.20
24	Rear Tailgate Inner Handle <i>new</i>	1	\$ 46.00	\$ 46.00
25	Rear Tailgate Inner Trim Board <i>contd</i>	1	\$ 388.60	\$ 388.60
26	Rear Tailgate Windscreen Moulding RH <i>3/4</i>	1	\$ 137.40	\$ 137.40
27	Rear Tailgate Windscreen Moulding LH <i>3/4</i>	1	\$ 137.40	\$ 137.40

28	Rear Tailgate Windscreen Moulding Lower <i>new</i>	1	\$	81.70	\$	81.70
29	Rear Tailgate Wiper Motor <i>new</i>	1	\$	512.00	\$	512.00
30	Rear Tailgate Stopper RH <i>new</i>	1	\$	18.00	\$	18.00
31	Rear Tailgate Stopper LH <i>new</i>	1	\$	18.00	\$	18.00
32	Rear End Panel <i>Deated</i>	1	\$	857.20	\$	857.20
33	Rear End Panel Top Garnish <i>Deated</i>	1	\$	135.00	\$	135.00
34	Rear Spare Tyre Panel <i>new</i>	1	\$	1,108.80	\$	1,108.80
35	Rear Spare Tyre Panel Top Board <i>new</i>	1	\$	168.00	\$	168.00
36	Rear Spare Tyre Panel Tools Box Sponge <i>new</i>	1	\$	310.00	\$	310.00
37	Rear Taillamp Assembly RH <i>new</i>	1	\$	502.40	\$	502.40
38	Rear Taillamp Lower Bracket RH <i>new</i>	1	\$	32.60	\$	32.60
39	Rear Taillamp Assembly LH <i>new</i>	1	\$	502.40	\$	502.40
40	Rear Taillamp Lower Bracket LH <i>new</i>	1	\$	32.60	\$	32.60
41	Rear Fender RH <i>new</i>	1	\$	1,054.00	\$	1,054.00
42	Rear Fender LH <i>new</i>	1	\$	1,054.00	\$	1,054.00
43	Rear Fender Wheel Arch Garnish RH <i>new</i>	1	\$	235.00	\$	235.00
44	Rear Fender Wheel Arch Garnish LH <i>new</i>	1	\$	235.00	\$	235.00
45	Rear Fender Inner Trim Board RH <i>new</i>	1	\$	548.00	\$	548.00
46	Rear Fender Inner Trim Board LH <i>new</i>	1	\$	548.00	\$	548.00
47	Rear Buzzer <i>new</i>	1	\$	108.00	\$	108.00
48	Rear Smart Key Antenna Sensor <i>new</i>	1	\$	162.40	\$	162.40
49	Rear Exhaust Pipe Assembly <i>new</i>	1	\$	821.00	\$	821.00
50	Rear Exhaust Pipe Assembly Heat Shield <i>new</i>	1	\$	154.00	\$	154.00
51	Rear Exhaust Pipe Mounting	2	\$	55.00	\$	110.00

Parts Sub Total : \$ 15,521.30

20% Discount \$ 3,104.26

PARTS TOTAL : \$ 12,417.04

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate <i>new</i>	1	\$ 50.00	\$ 50.00
2	Rear Bumper Clips - Set <i>new</i>	1	\$ 50.00	\$ 50.00
3	Rear Taillamp Clips - Set <i>new</i>	1	\$ 50.00	\$ 50.00
4	Rear Tailgate Reflector Lamp Clips - Set <i>new</i>	1	\$ 50.00	\$ 50.00
5	Rear End Panel Top Garnish Clips - Set <i>new</i>	1	\$ 50.00	\$ 50.00
6	Rear Fender Inner Shield Clips - Set <i>new</i>	1	\$ 80.00	\$ 80.00
7	Rear Fender Inner Trim Board Clips - Set <i>new</i>	1	\$ 100.00	\$ 100.00
8	Rear Tailgate Sealant <i>new</i>	1	\$ 150.00	\$ 150.00
9	Rear End Panel Sealant <i>new</i>	1	\$ 150.00	\$ 150.00
10	Rear Spare Tyre Panel Sealant <i>new</i>	1	\$ 150.00	\$ 150.00
11	Rear Fender RH Sealant <i>new</i>	1	\$ 150.00	\$ 150.00

12	Rear Fender LH Sealant <i>Abc new</i>	1	\$	150.00	\$ 150.00 <i>150.00</i>
13	Rear Tailgate Windscreen Glass Sealant <i>new</i>	1	\$	150.00	\$ 150.00 <i>60</i>
14	Rear Tailgate Inner Trim Board Clips - Set <i>new</i>	1	\$	50.00	\$ 50.00 <i>30</i>
15	Rear Tailgate Outer Garnish Clips - Set <i>new</i>	1	\$	50.00	\$ 50.00 <i>+</i>
16	Rear Fender Wheel Arch Garnish Clips - Set <i>new</i>	1	\$	100.00	\$ 100.00 <i>+</i>
17	Rear Bumper Reverse Sensor - Set <i>2nd</i>	1	\$	350.00	\$ 350.00 <i>200</i>
18	Rear Tailgate Reverse Camera <i>new</i>	1	\$	500.00	\$ 500.00 <i>+</i>
SPECIAL NETT TOTAL :					\$ 2,380.00

Nos.	LABOUR	TOTAL S\$	
1	To Panel Beat, Remove & Refix Parts	\$ 2,400.00 <i>700</i>	2,400.00
2	To Spray Paint Affected Areas	\$ 1,800.00 <i>600</i>	1,800.00
3	Wiring & Bulb Check	\$ 100.00 <i>30</i>	100.00
4	To Remove & Refix Rear Tailgate Windscreen Glass	\$ 150.00 <i>120</i>	150.00
5	To Transfer Tailgate Mechanism	\$ 150.00 <i>60</i>	150.00
6	To Remove & Refix Rear Tailgate Reverse Camera	\$ 150.00 <i>50</i>	150.00
7	To Remove & Refix Rear Bumper Reverse Sensor	\$ 120.00 <i>50</i>	120.00
8	To Remove & Refix Rear Exhaust Pipe	\$ 150.00 <i>+</i>	150.00
9	To Remove & Refix Fuel Tank	\$ 250.00 <i>+</i>	250.00
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 150.00 <i>60</i>	150.00
11	To apply anti rust on affected parts	\$ 150.00 <i>60</i>	150.00
12	To Conduct Water Leak Test	\$ 100.00 <i>+</i>	100.00
13	To Send Diagnostic & Reset Control Unit. Programming & Calibration	\$ 480.00 <i>+</i>	480.00
LABOUR TOTAL :		\$ 6,150.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS TOTAL :	\$	12,417.04
SPECIAL NETT TOTAL :	\$	2,380.00
LABOUR TOTAL :	\$	6,150.00
GRAND TOTAL :	\$	20,947.04

Adrian Lj
2/5 09/09/24
06 Days

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	402W

Vehicle Details

Vehicle No.:	SLJ6111D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Sep 2024
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15B4408992
Chassis No.:	RU11208992
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,680.00
Original Registration Date:	19 Dec 2016
First Registration Date:	19 Dec 2016
Transfer Count:	2
Actual ARF Paid:	\$12,352.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2026
PARF Rebate Amount:	\$7,411.00

Intended COE Rebate Details

COE Expiry Date:	18 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,000.00
COE Rebate Amount:	\$11,451.00
Total Rebate Amount:	\$18,862.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 03 Sep 2024

OK