

AUTOLUTION INDUSTRIAL PTE LTD  
19 UBI ROAD 4  
SINGAPORE 408623  
TEL: 6490 9666 FAX: 6846 7483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0304/24  
DATE : 02-SEP-2024

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
S(079909)  
TEL : 63896111  
FAX : 62247175

OWNER'S NAME : TIO WEE KUN(P0073/0504/TP)  
ADDRESS : BLK 10 BEDOK RESERVOIR VIEW, THE CLEARWATER  
#13-28  
S(479236)  
TELEPHONE NO : 90182586

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : \*  
VEHICLE NO : SKQ807U  
MODEL CODE : BDTARCZB17EWA----A  
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)  
ENGINE NO : HR16950465B  
CHASSIS NO : MNTBBAB17Z0020462  
MILEAGE : 108538 KM  
DATE IN : 02/09/2024  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : HAMZAH  
ACCIDENT DATE : 31/08/2024

*Not Authorized  
on  
5/9/24  
marus  
HP90096608  
value 1st. before party.  
4 days*

*P/P # 2822-76*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKQ807U  
-----

| S/NO                 | JOB CODE | NATURE OF JOB                                                                      | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATION |
|----------------------|----------|------------------------------------------------------------------------------------|----------------------|------------------------------|
| 1                    | ZZ/001   | LABOR CHARGES TO REPAIR RH REAR DOOR, RH REAR<br>FENDER AND RENEW REAR BUMPER. 430 | 1100.00              | 645                          |
| 2                    | ZZ/002   | CHARGES TO SPRAY PAINTING SAME. 350                                                | 1300.00              | 1050                         |
| 3                    | ZZ/003   | REMOVE AND INSTALL REVERSE SENSOR AND RESET.                                       | 55.00                | ✓                            |
| 4                    | ZZ/004   | RENEW RH REAR WHEEL RIM AND BALANCING.                                             | 15.00                | ✓                            |
| TOTAL LABOUR CHARGES |          |                                                                                    | 2470.00              |                              |

1765

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKQ807U

|                                                       |                                | DAMAGED PARTS & PRICES |         |        |              |
|-------------------------------------------------------|--------------------------------|------------------------|---------|--------|--------------|
| S/NO                                                  | PARTS DESCRIPTION              | PARTS NUMBER           | NETT    | LIST   | S/NETT REMAR |
| 1                                                     | SUNDRIES                       | NPN                    |         | 17     | 50.00 X      |
| 2                                                     | REAR WHEEL RIM RH              | 40300-SSW166           |         | 647    | 320.00 ✓     |
| 3                                                     | RH REAR COMB LAMP              | 26550-3SB0B            | 17      | 415.60 | X            |
| 4                                                     | R/R FENDER CORNER STICKER      | 78864-3SB0A            | 17      | 33.60  | ✓            |
| 5                                                     | RH REAR CLOSING PLATE          | 78818-3SB0A            | 17      | 38.10  | X            |
| 6                                                     | REAR BUMPER SIDE BRKT RH       | 85226-3ST1A            | 17      | 38.60  | X            |
| 7                                                     | CLIP REAR BUMPER @ \$1.50 EACH | 01553-10501            | 17      | 30.00  | ✓            |
| 8                                                     | REAR BUMPER FASCIA             | 85022-3ST4H            | 647/22  | 858.60 | ✓            |
| SUB TOTAL                                             |                                |                        | 1414.50 | 0.00   | 370.00       |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) |                                |                        | 282.90  | 0.00   | 0.00         |
| GRAND TOTAL                                           |                                |                        | 1131.60 | 0.00   | 370.00       |
| OVERALL TOTAL                                         |                                |                        | 1501.60 |        |              |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKQ807U

|                           |           |
|---------------------------|-----------|
| TOTAL LABOUR CHARGES      | 2470.00   |
| TOTAL SPARE PARTS CHARGES | 1501.60   |
| GRAND TOTAL               | 3971.60 * |

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

|                 |   |      |
|-----------------|---|------|
| NAME            | : |      |
| SURVEYED DATE   | : |      |
| AUTHORIZED DATE | : |      |
| EXCESS CLAUSE   | : | 0.00 |
| LIABILITY       | : | 0.00 |
| REMARKS         | : |      |

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.