

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0304/24

DATE : 02-SEP-2024

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

*Not Authorized
on
5/9/24
marus
HP90096608
where it is before party.
4 days*

OWNER'S NAME : TIO WEE KUN(P0073/0504/TP)
ADDRESS : BLK 10 BEDOK RESERVOIR VIEW, THE CLEARWATER
#13-28
S(479236)
TELEPHONE NO : 90182586

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SKQ807U
MODEL CODE : BDTARCZB17EWA----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR16950465B
CHASSIS NO : MNTBBAB17Z0020462
MILEAGE : 108538 KM
DATE IN : 02/09/2024
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 31/08/2024

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKQ807U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR RH REAR DOOR, RH REAR FENDER AND RENEW REAR BUMPER. 432	1100.00	645
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME. 350	1300.00	1050
3	ZZ/003	REMOVE AND INSTALL REVERSE SENSOR AND RESET.	55.00	✓
4	ZZ/004	RENEW RH REAR WHEEL RIM AND BALANCING.	15.00	✓
TOTAL LABOUR CHARGES			2470.00	

1765

2822.76

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKQ807U

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMAR
1	SUNDRIES	NPN		50.00 ?
2	REAR WHEEL RIM RH	40300-SSW166	R	320.00 X
3	RH REAR COMB LAMP	26550-3SB0B	in 415.60 X	
4	R/R FENDER CORNER STICKER	78864-3SB0A	nee 33.60	
5	RH REAR CLOSING PLATE	78818-3SB0A	38.10 ?	
6	REAR BUMPER SIDE BRKT RH	85226-3ST1A	38.60 ?	
7	CLIP REAR BUMPER @ \$1.50 EACH	01553-10501	nee 30.00	
8	REAR BUMPER FASCIA	R 85022-3ST4H	858.60 X	
SUB TOTAL			1414.50	0.00 370.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			282.90	0.00 0.00
GRAND TOTAL			1131.60	0.00 370.00
OVERALL TOTAL			1501.60	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKQ807U

TOTAL LABOUR CHARGES	2470.00
TOTAL SPARE PARTS CHARGES	1501.60

GRAND TOTAL	3971.60 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.