

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

## ESTIMATE OF REPAIR

Veron

Veh# : SNQ3859P

Model:

TOYOTA NOAH

Accident Date : 13/6/2024

Location : PIE EXIT THOMSON RD

3P:

GBF5901L (INCOME)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear tailgate <i>Painted</i>	<del>2,772.40</del>	2190	
2	1 pc	Rear tailgate windscreen moulding <i>new</i>	104.60	-	
3	1 pc	Rear tailgate windscreen sealant <i>new</i>		40.00	-
4	1 pc	Rear tailgate emblem - NOAH <i>Atac to new</i>	87.30	+	
5	1 pc	Rear tailgate reflector lamp RH <i>new</i>	710.30	+	
6	1 pc	Rear tailgate reflector lamp gasket seal RH <i>new</i>	30.00	+	
7	1 pc	Rear tailgate inner trim garnish <i>could</i>	<del>937.00</del>	758	
8	1 set	Rear tailgate inner trim garnish clip <i>new</i>		<del>50.00</del>	30
9	2 pcs	Rear tailgate guide rubber stopped R/L <i>new</i>	13.00	+	
10	1 pc	Rear tailgate weatherstrip seal <i>new</i>	476.60	+	
11	1 pc	Rear tail lamp RH <i>new</i>	959.40	+	
12	1 set	Rear tail lamp clip RH <i>new</i>		<del>6</del> 40.00	+
13	1pc	Rear tail lamp lower garnish Rh <i>new</i>	372.00	+	
14	1pc	Rear tail lamp lower garnish retainer Rh <i>new</i>	139.90	+	
15	1 pc	Rear bumper <i>Distorted</i>	836.30	✓	
16	1 pc	Rear bumper tow cover Rh <i>del</i>	50.60	-	
17	1 pc	Rear bumper side retainer Rh <i>new</i>	265.80	+	
18	1 pc	Rear bumper Rh reflector <i>could</i>	90.00	✓	
19	1 set	Rear bumper clip <i>new</i>		<del>50.00</del>	30
20	1 pc	Rear bumper reverse sensor center Rh <i>new Rh d</i>	582.70	<del>200</del>	
21	1 pc	Rear bumper reverse sensor Rh <i>new d</i>	470.50	200	
22	4 pcs	Rear bumper reverse sensor holder bracket <i>new</i>	78.80	+	50
23	1 pc	Rear bumper emblem - hybride <i>new</i>		<del>90.00</del>	
24	1 pc	Rear end panel <i>Painted</i>	<del>1,056.00</del>		

795

25	1 pc	Rear end panel middle stay panel <i>new</i>	832.00	+	
26	1 pc	Rear end panel inner top garnish <i>Delco</i>	214.10	✓	
27	1 set	Rear end panel inner top garnish clip <i>new</i>		30.00	10
28	1 pc	Rear end panel Antenna sensor <i>new</i>	132.70	+	
29	1 pc	Rear fender inner trim garnish RH <i>new</i>	1297.35	+	
30	1 set	Rear fender inner trim garnish clip <i>new</i>		50.00	+
31	1 pc	Rear floor center top board cover <i>from car</i>	600.70	-	
		<i>6039.30</i> Sub Total:	13,110.05	350.00	0.00
		<i>4529.47</i> <i>S/N: 160</i>	25%	0%	10%
		After Less %:	<b>9,832.54</b>	<b>350.00</b>	<b>0.00</b>
<b>Labour</b>					
1		To remove & refix accident damaged parts & realign accident affected area.	<del>1,400.00</del>		<i>700</i>
2		To spray paint on accident affected area.	<del>1,000.00</del>		<i>600</i>
3		To remove & refix rear tailgate windscreen glass.	<del>150.00</del>		<i>120</i>
4		To remove & refix <del>door</del> <i>tailgate</i> mechanism & check for function.	<del>80.00</del>		<i>60</i>
5		To remove & refix rear seat, side covering, trim garnish & other attachment parts.	<del>150.00</del>		<i>60</i>
6		To check wiring & rewire parking sensor. <i>1650</i>	<del>100.00</del>		<i>50</i>
7		To rust proof affected area.	<del>90.00</del>		<i>60</i>
8		To diagnosis & reset after work.	250.00		+
		Sub Total:	<b>3,220.00</b>		
		<b>Total:</b>	<b>13,402.54</b>		

*Chan*

Chan San Choon  
Director  
DipEng, AAE MIMI, MSAE(Aust)

*Total: 6339.47 Admin Lij*  
*L/S: SK ✓ L/S 19/06/24*  
*06 Days*



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: